THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

January 20, 2	O17 Signature on File	For Custodial Supervisor Use Only
TO:	Thaddeus Smith, Principal Horizon Elementary	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Daniel Meyer, Project Manger Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On January 19, 2017, I conducted an assessment at **Horizon Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

DM:smn Enc.

cc: Shelley Meloni, Director, Pre-Construction

Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division

Broward Teachers Union

Federation of Public Employees

Gerald Devio, Supervisor II Custodial

Benjamin Osborne, Supervisor II Custodial

Mark Murray, Supervisor II Custodial

Sam Bays, Director, Maintenance Operations

Kurt Wirz, Area Manager Trades

Replace stained ceiling tiles after roofing repairs	
Clean Supply Grills with Wexcide	
Reduce items in classroom	
Store items in plastic containers with lids	
	▼
	▼
	▼
	▼

Corrective Actions to be completed by 11 C	
Repair Cause of Stained Ceiling Tiles	▼
Ceiling tile cuts needed around supply vents	
	▼
	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Horizon Elen	nentary Evaluation Dat	e January 19, 2017	Time of Day 1:00 PM
Outdoor Conditions Temperature	e 82.1 Relative	Humidity 48.6	Ambient CO2 465
Fish Temperature Range 850 71.2 72 - 78		Range CO ² 2412	Range # Occupants MAX 700 > 20 Ambient
Noticeable Odor No Ceiling 2' X 4' Lay in	Visible water damage / staining? Yes	Visible microbial growth?	Amount of material affected 4 tiles
Walls Cloth/Drywall Floor 12" x 12" Vinyl	Yes	Yes No	Above door (West wall)
Ceiling Clean Walls Clean Flooring Clean Room Surfaces Clean Yes Yes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	No Yes No	HVAC Return Grills Clean Inside of Return Duct Clean No
Trash Removed No Signs of Pests No Room Cluttered Yes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A Yes Yes	Unapproved Chemicals / No Cleaners in Room Air Fresheners in Room
Mechanical Equipment Location Bar Filters Installed Properly Yes Condensate Pan Clean Yes	rd like HVAC system in clas Filters Clean Cooling Coil Clean		Mechanical Room Clean N/A nside of HVAC Unit Clean No
Fresh Air Intake Location Pollutant Sources Near Air Intake	ck of the unit	▼	Fresh Air Intake Free of Obstruction Yes
Observations Water stained ceiling tiles. Rusted to be replaced. Return air grill needs to be vacuumed.			

Corrective Actions to be Completed by Site Based Staff

Constitution to the Completion by One Ducou Co	
Replace stained ceiling tiles after roofing repairs	
Clean Supply Grills with Wexcide	
Remove return grill and vacuum	▼
	▼
	▼
	lacksquare
	lacksquare
	▼

Corrective Actions to be Completed by PPO

Corrective Actions to be Completed by FFO	
Repair Cause of Stained Ceiling Tiles	
Ceiling tile cuts needed around supply vents	
Replace ceiling t-bar	▼
Remove wet drywall and replace	▼
Repair HVAC to reduce CO2 level in classroom	
	▼
	▼
	▼