## **HUNT JAMES S ELEMENTARY**

Walkthrough Date: 03/30/2007 Temp RH CO2
Outdoor Parameters: 75.4 59.8 581

Room	Priority	Responsible	Answer	Recommendation
101	Inside Parameters:	Тетр	RH	CO2
		72.6	57.2	1039
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
113	Inside Parameters:	Temp	RH	CO2
		73.6	56.4	916
	1	Site	Non-approved chemicals scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
114	Inside Parameters:	Temp	RH	CO2
		72.8	59.0	874
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
	Inside			

				1 age 2 of e
115	Parameters:		!!!	CO2
		70.4	60	892
	2	Site	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
Room	Priority	Responsible	Answer	Recommendation
121	Inside Parameters:	Тетр	RH	CO2
		70.9	59.1	1006[
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	2	Site	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
Room	Priority	Responsible	Answer	Recommendation
123	Inside Parameters:	Temp	RH	CO2
		71.3	58.2	9904
	2	Site	Return vents closed at the time of assessment.	Facilities serviceperson to open return vents.
Room	Priority	Responsible	Answer	Recommendation
127	Inside Parameters:	Temp	RH	CO2
	!!!	72.7	62.6	847
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
129		Тетр	RH	CO2

	Parameters:			
		71.1	67.3	885
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	Humidity was slightly elevated at the time of assessment. Humidity slightly exceeded target range however indoor humidity was more than 10% lower than the outside reading which is evidence that the ventilation system is dehumidifying fresh air.	Site based facilities serviceperson should monitor this room.
Room	Priority	Responsible	Answer	Recommendation
134	Inside Parameters:	Тетр	RH	CO2
		70.2	69.1	846
	2	Site	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
139	Inside Parameters:	Тетр	RH	CO2
		72.4	61.8	969
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with
	2	Site .	11 7 0	District approved germicidal cleaner.
Room	Priority	Responsible	7.7.0	Recommendation
<b>Room</b> 142	1	11	7.7.0	
	Priority Inside Parameters:	Responsible	Answer	Recommendation

Site based administration to encourage facility serviceperson

	2	Site	Temperature was low at the time of assessment.	staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
Room	Priority	Responsible	Answer	Recommendation
144	Inside Parameters:	Temp	RH	CO2
		70.2	64.9	946
	2	Site	Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	Art supplies in room.	Curriculum supervisor meet with appropriate staff to address issues of concern and ensure that all supplies are approved for use and handled/stored in a manner consistent with District procedures.
Room	Priority	Responsible	Answer	Recommendation
176	Inside Parameters:	Тетр	RH	CO2
	arameters.			
	l arameters.		59.6	865
	2		59.6 Slight dust accumulation was observed on environmental surfaces at the time of assessment.	
		74.6	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	865 Site based administration should address general cleanliness
Room	2	74.6 Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.	Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to evaluate cause of odor and inspect
<b>Room</b> 503	2	74.6 Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.	Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.
	2 2 Priority Inside	74.6 Site Site Responsible	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.  Answer  RH	Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.  Recommendation
	2 2 Priority Inside	74.6 Site Site Responsible Temp	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.  Answer  RH	Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.  Recommendation  CO2
	2 2 Priority Inside Parameters:	74.6 Site Site Responsible Temp 73.6	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.  Answer  RH  56.6  Slight dust accumulation was observed on environmental	Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.  Recommendation  CO2  890  Site based administration should address general cleanliness
503	2 2 Priority Inside Parameters:	74.6 Site Site Responsible Temp 73.6 Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.  Answer  RH  56.6  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.  Recommendation  CO2  890  Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to thoroughly clean and sanitize with

		72.6	54.4	936
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
506	Inside Parameters:	Тетр	RH	CO2
		72.8	55.4	958
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
	ا ال			
508	Inside Parameters:	Тетр	RH	CO2
508		Тетр		
508		Тетр	RH	CO2
508	Parameters:	Temp 73.1	RH  56.5  Slight dust accumulation was observed on environmental	CO2  945  Site based administration should address general cleanliness
	Parameters:  2	Temp 73.1 Site	RH  56.5  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.	CO2  945  Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to thoroughly clean and sanitize with
	Parameters: 2 2	Temp 73.1 Site Site Responsible Temp	RH  56.5  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.  Answer  RH	CO2  945  Site based administration should address general cleanliness with facility serviceperson staff. Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.  Recommendation  CO2
Room	Parameters:  2 2 Priority Inside	Temp 73.1 Site Site Responsible Temp	RH  56.5  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.  Answer  RH	CO2  Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.  Recommendation
Room	Parameters:  2 2 Priority Inside	Temp 73.1 Site Site Responsible Temp	RH  56.5  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.  Answer  RH	CO2  945  Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.  Recommendation  CO2
Room	Parameters:  2  2  Priority  Inside Parameters:	Temp  73.1  Site  Site  Responsible  Temp  73.1	RH  56.5  Slight dust accumulation was observed on environmental surfaces at the time of assessment.  Dust observed on supply register at the time of assessment.  Answer  RH  54.2  Slight dust accumulation was observed on environmental	CO2  945  Site based administration should address general cleanliness with facility serviceperson staff.  Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.  Recommendation  CO2  1013  Site based administration should address general cleanliness

	2	Site	Ceiling tiles broken, damaged or missing.	Facilities serviceperson to replace ceiling tiles.
Room	Priority	Responsible	Answer	Recommendation
604	Inside Parameters:	Тетр	RH	CO2
		73.7	55.9	1067
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
703	Inside Parameters:	Тетр	RH	CO2
		74.1	48.1	1188
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
704A	Inside Parameters:	Тетр	RH	CO2
		74.3	47.7	1184
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
705	Inside Parameters:	Тетр	RH	CO2
		74.4	47.9	1232
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.

				Page / of 8
Room	Priority	Responsible	Answer	Recommendation
706	Inside Parameters:	Temp	RH	CO2
		75.1	48.8	1296
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
707	Inside Parameters:	Temp	RH	CO2
		73.7	48.7	1237
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
852	Inside Parameters:	Temp	RH	CO2
		75.6	62.2	746
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
855	Inside Parameters:	Temp	RH	CO2
		74.1	58.3	752
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
Room	Priority	Responsible	Answer	Recommendation
856	Inside Parameters:	Temp	RH	CO2
		74.6	60.1	1030
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.

2 Site

Dust observed on supply register at the time of assessment. Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.