

managing risk with responsibility

	ement Department	Fax: 754 321-1900		
October 20, 2014 Signature on File		For Custodial Supervisor Use Only		
TO:	Thomas Schroeder, Principal Margate Elementary School	Custodial Issues Addressed		
FROM:	Dan Meyer, Project Manager Risk Management Department	Custodial Issues Not Addressed		
SUBJECT:	Indoor Air Quality (IAQ) Assessment			

On October 16, 2014, I conducted an assessment at **Margate Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

DM/tc Enc.

IAQ Assessment

Margate	Elementary Evaluation Dat	October 16, 2014	Time of Day 1:30
Outdoor Conditions Tempera	ature 84.6 Relative	Humidity 53.1	Ambient CO2 457
		Range <u>CO</u> % - 60% 507	
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected
Ceiling 2' X 4' Lay in	Yes	No	2 tiles
Walls Concrete/drywall	No	No	
Floor 12" x 12" Vinyl	No	No	
Ceiling Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean Yes
Walls Clean Yes Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean Yes
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes	
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room Yes
Signs of Pests No Room Cluttered No	Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners Yes in Room
Mechanical Equipment Location	In classroom HVAC unit		Mechanical Room Clean N/A
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean Yes
Condensate Pan Clean N/A	Cooling Coil Clean	Yes	
Fresh Air Intake Location ☐ Ducted to roof-top ☐ Fresh Air Intake Free			
Pollutant Sources Near Air Intake	No	▼	of Obstruction Yes
Observations			
REASSESSMENT - Chilled water leaks in classroom - 2 tiles are volumes need to be removed. Old	vet and need to be replaced. Cla	assroom is also used	•

Corrective Actions to be Completed by Site Based Staff

	_			
Remove cardboard boxes. Store items in plastic.				
Remove non-approved chemicals				
Remove non-approved air-fresheners	▼			
	▼			
	▼			
	▼			
	▼			
	▼			

Corrective Actions to be Completed by PPO

Remove insulation inside HVAC system, microbial			
Repair cause of stained ceiling tiles (ROOF)			
Evaluate cause of staining on East wall	▼		
Repair/replace wall material as necessary			
	▼		
	▼		
NOTE: Previous assessment conducted in April	▼		
2014 and WO EQ08001 generated for insulation			
-			