## **Tools for Schools Phase IX - Indoor Air Quality**

## **Follow-up Action Plan for Site**

**Norcrest Elementary 0561** 81.5 66 440

Walkthrough Date: 5/3/2012 Temp RH Co2
Outside Measurements



| Room | Priority | Concern | Response   | Recommendation   |
|------|----------|---------|--|--|
| 722  | 2 X      |         | Live plants in room.                                 | Remove live plants from room. Soil is a source of microbial growth.              |
| 722  | 2 X      |         | Dust and debris on HVAC supply and/or return grills. | Clean HVAC supply and/or return grills with District approved germicidal cleaner |
| 722  | 2 X      |         | Excessive clutter in room.                           | Encourage occupant to reduce clutter in room to assist with cleaning efforts.    |
| 724  | 2 X      |         | Dust and debris on HVAC supply and/or return grills. | Clean HVAC supply and/or return grills with District approved germicidal cleaner |
| 724  | 2 X      |         | Pests were identified at the time of the assessment. | Generate a work order through COMPASS for Pest Control Services.                 |
|      |          |         | Ants and droppings along windows.                    |  |
| 732  | 2 X      |         | Dust and debris on HVAC supply and/or return grills. | Clean HVAC supply and/or return grills with District approved germicidal cleaner |
| 732  | 2 X      |         | Broken ceiling tiles.                                | Remove and replace broken ceiling tiles.   |
| 732  | 2 X      |         | Excessive clutter in room.                           | Encourage occupant to reduce clutter in room to assist with cleaning efforts.    |