

Tools for Schools Phase IX - Indoor Air Quality

Follow-up Action Plan for PPO



Norcrest Elementary

0561

81.5 66 440

Walkthrough Date: 5/3/2012

Temp RH Co2
Outside Measurements

Room	Priority	Concern	Response	Recommendation
722	2	X	Deteriorated caulk at sink area in restroom.	Caulk around sink area in restroom.
722A	2	X	Faucet leaking in restroom.	Evaluate and repair sink faucet in restroom.
724	2	X	Temperature was not within range at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
732	2	X	Exhaust fans not operating properly.	Evaluate exhaust fans and repair as appropriate.
732	2	X	Dry erase board damaged and in need of replacement.	Remove and replace dry erase board.