


Category		Detail	Assessment Comments	Recommended Corrective Action
213	72 Temp	52% Co2		
	General Cleanliness		2 stained ceiling tiles.	Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
	General Cleanliness	Check for pests.	Food found in classroom	Remove food and candy.
General Cleanliness Thermal Comfort			Tile floors dirty and stained. Surfaces very dusty.	Properly clean flooring and surfaces. Replace stained ceiling tile.
		General items to watch for.	No problem with comfort any longer.	No corrective action recommended at this time.
	<i>Temp</i> General Cleanliness	RH Co2	There were no problems observed at	No corrective action recommended at this
	General Cleanliness		time of assessment. Floors stained and dirty, surfaces dusty. Cluttered classroom.	time. Custodial staff should thorougly clean all environmental surfaces and floor within classroom.
	Thermal Comfort	General items to watch for.	The humidity was 52% at the time of assessment. The desired humidity level is below 60%. Temperature was in acceptable range at time of assessment.	No corrective action recommended at this time.
215	71	51%		
	Temp	RH Co2		
General Cleanliness				


	Category	Detail	Assessment Comments	Recommended Corrective Action
	General Cleanliness		Flooring dirty and stained. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floors within classroom.
	Thermal Comfort	Humidity level.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
	Thermal Comfort	General items to watch for.	1 stained ceiling tile fixture with water stained lens.	Repair roof leaks and stained ceiling tile.
216	73 Temp	54% Co2		
	General Cleanliness	Check for pests.	Honey, cookies, candy, crackers found in room.	Remove all food from room.
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
218	73 Temp	54% Co2		
	General Cleanliness		Standing water on sink counter.	Clean spills promptly.
	General Cleanliness Thermal Comfort	Check for pests. General items to watch for.	Cookies under sink. Temperature was within acceptable range at time of assessment.	Remove food from room. No corrective action recommended at this time.
21	73 Temp	53% RH Co2		
	General Cleanliness	Check for pests.	No pests found at time of assessment.	No corrective action recommended at this time.


	Category	Detail	Assessment Comments	Recommended Corrective Action
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	
	Ventilation	Determine how your classroom is ventilated.	1 return, 1 supply.	No corrective action recommended at this time.
	Ventilation			Repair/Replace water damaged walls.
		Classroom is too cold. Children complain at times	and have difficulty concentrating due to the	discomfort.
226	74	50%		
	Temp	RH Co2		
	General Cleanliness	Check for pests.	Sugar, cookies, crackers in cabinet.	Remove food from rooms.
	General Cleanliness	Confirm that the classroom is cleaned properly	Floor tile stained and dirty. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floor tile withir classroom.
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
228	73	49%		
	Temp	RH Co2		
	General Cleanliness	Check for pests.	No pests found at time of assessment.	No corrective action recommended at this time.
	General Cleanliness	Confirm that the classroom is cleaned properly	Floor tile dirty, stained. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floor tile withir classroom.
	General Cleanliness	Clean spills promptly.	Floors stained.	Properly clean flooring.
	Thermal Comfort	General items to watch for.	Temperature was within acceptable	No corrective action recommended at this



	Category	Detail	Assessment Comments	Recommended Corrective Action		
242	72	51%				
	Тетр	RH Co2				
	Drain Traps in the Classroom	Drain traps, if present, can become a problem when the water in the drain trap evaporates due to infrequent use, allowing sewer gases to enter the room.	Trap wet, no problem found.	No corrective action recommended at this time.		
	General Cleanliness	Check for pests.	Insects in light fixtures.	Maintenance needs to establish work orde to inspect room for pests and implement appropriate corrective action.		
	General Cleanliness	Clean spills promptly.	Standing water on counter by sink.	Clean spills promptly.		
	General Cleanliness	Confirm that the classroom is cleaned properly	Floor tile stained and dirty. Surfaces dusty.	Properly clean flooring and surfaces.		
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.		
		When accidents occur within the classroom (bathroom), who is responsible and how long do we wait before we call up front again?				
243	72	50%				
	Temp	RH Co2				
	Exterior Inspection	General considerations for roof.	Ceiling tiles stained. Multiple stained tiles throughout school.	Check roof for leaks.		
	General Cleanliness	Check for pests.	Various areas have signs of insects.	Site based staff is to remove all food from classrooms. Maintenance is to treat buildings.		
	General Cleanliness	Confirm that the classroom is cleaned properly	Floor tile stained and dirty. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floors within classroom.		
	Interior Inspection	General considerations for classrooms and other areas.	Entire facility return grills dusty. Ceiling tiles at supply grills dusty.	Clean all HVAC grills.		
	Thermal Comfort	Humidity level.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.		
			· · · · · g · · · · · · · · · · · · · ·			

Friday, August 19, 2005





	Category		Detail	Assessment Comments	Recommended Corrective Action
M851	76	57%			
	Temp	RH	Co2		
G	ieneral Cleanliness			Hole in ceiling tile cut for smoke detector, not installed in that tile.	Replace ceiling tile.
G	ieneral Cleanliness	Con prop	firm that the classroom is cleaned erly	Floor tile stained and dirty. Damaged and chipped.	Site based staff to clean and wax floor. Facilities to repair/replace damaged floor.