

managing risk with responsibility

Aston A. Henry, Director Risk Management Department
 Telephone:
 754 321-1900

 Fax:
 754 321-1917

October 13, 2	2014 Signature	on File For Custodial Supervisor Use Only
TO:	Michelle Garcia, Principal Oakland Park Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Robert Krickovich, Coordinator I, L Risk Management Department	EA
SUBJECT:	Indoor Air Quality (IAQ) Assessme	nt

On October 1, 2014, I conducted an assessment at **Oakland Park Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RK/tc Enc.

	IAQ Assess	ment		
Oakland F	Park Elementary Evaluation Date	te October 1, 2014	Time of Day	2:45
Outdoor Conditions Tem	perature 90.3 Relative	e Humidity 61.6	Ambient CO2	
FishTemperature133477.5		Range <u>CO</u> 2 % - 60%	Range # Oo MAX 700 > Ambient	ccupants 3
Noticeable OdorNoCeiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Visible water damage / staining? No No No	Visible microbial growth? No No	Amount of material affected	
Ceiling CleanYesWalls CleanYesFlooring CleanNoRoom Surfaces CleanYes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes	HVAC Return Grills Clean Inside of Return Duct Clean	Yes
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A N/A N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
	ion Bard unit in room Yes Filters Clean N/A Cooling Coil Clean	Yes N/A	Mechanical Room Clean Inside of HVAC Unit Clean	N/A N/A
Fresh Air Intake Location Pollutant Sources Near Air Intake	Outside of Room Trees	▼ ▼	Fresh Air Intake Free of Obstruction	Yes

Observations

Teacher has to leave door to corridor open to cool room down - Ceiling tile front of left most window panel replaced in August was not cut properly and does not fit in opening - A/C unit not operating - heat coming out of return grill on unit (turned off disconnect and called PPO) - Sign on A/C unit reads "Failed condenser coil, very high head pressure, unit resets / then off / high head, part ordered 8/27/14 #3175" - Teacher stated that the A/C mechanic told her when the unit stops blowing cold air to turn off the breaker and wait a couple minutes then turn the breaker back on (NOT acceptable practice)

Corrective Actions to be Completed by Site Based Staff

Cut ceiling tile to fit properly	▼
	▼
	▼
	•
	•
	•
	▼
	•

Corrective Actions to be Completed by PPO

Train mechanics not to have teachers operating	▼
electrical disconnects (SAFETY ISSUE)	▼
	▼
Repair HVAC in this room and FISH 1338	▼
Both teachers were advised parts were ordered	▼
in August and units are still not repaired	▼
Room 1338 Thermostat was set for 76	▼
room temperature was 80	▼