# THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

### **TELEPHONE (754) 321-4200**

#### FACSIMILE: (754) 321-4285

January 14	4, 2016 Signature on File	For Custodial Supervisor Use Only
TO:	Thomas Redshaw, Principal <b>Park Trails Elementary</b>	Custodial Issues Addressed
FROM:	Robert Krickovich, Coordinator, LEA Environmental Health & Safety Department	Custodial Issues Not Addressed
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On January 13, 2016, I conducted an assessment at **Park Trails Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

cc: Shelley Meloni, Director, Pre-Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Broward Teachers Union Federation of Public Employees Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Rich Volipi, Supervisor II Custodial Mark Murray, Supervisor II Custodial Sam Bays, Director, Maintenance Operations Kurt Wirz, Area Manager Trades

RK/je Enc.

	IAQ Assessi	ment		
Park Trails	Elementary Evaluation Dat	e January 13, 2016	Time of Day 11:	30 AM
Outdoor Conditions Tempera	ture 70.4 Relative	Humidity 53.4	Ambient CO2 4	16
		Range CO <sup>2</sup> % - 60% 466	Range # Oo MAX 700 > Ambient	2
Noticeable OdorNoCeiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	Visible water damage / staining? No No No	Visible microbial growth? No No	Amount of material affected	
Ceiling Clean Yes Walls Clean Yes Flooring Clean No Room Surfaces Yes Clean	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes No	HVAC Return Grills Clean Inside of Return Duct Clean	No No
Trash RemovedYesSigns of PestsNoRoom ClutteredYes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	No Yes N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly Yes Condensate Pan Clean Yes	7	Yes Yes	Mechanical Room Clean Inside of HVAC Unit Clean	Yes Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Outside of Room None	<ul><li>▼</li></ul>	Fresh Air Intake Free of Obstruction	Yes
Observations Ceiling tiles and light fixtures at HVAC Supply grills dirty - Dirt / dust / debris on floor - Spotty microbial growth on underside of student tables - Papers / boxes/ plastic storage tubs on al counters, shelves and floor in room - Room to cluttered to clean properly.				

## Corrective Actions to be Completed by Site Based Staff

Thoroughly clean and sanitize flooring	▼
Clean underside of tables with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Clean light fixtures around HVAC supply grills	▼
Encourage occupant to reduce clutter	▼
	▼
	▼
	▼

# **Corrective Actions to be Completed by PPO**

Evaluate and repair HVAC system as needed	▼
Check all controls / dampers / interlocks	▼
Repair exhaust fan in 163A	▼
Set Temperature to 72 - 78 degrees	▼
	▼
	▼
	▼
	▼

	IAQ Assessr	nent		
Park Trails	Elementary Evaluation Date	e January 13, 2016	Time of Day 11:	30 AM
Outdoor Conditions Temper	ature 70.4 Relative	Humidity 53.4	Ambient CO2 4	16
		Range CO <sup>2</sup> % - 60% 484	Range # O MAX 700 > [ Ambient	ccupants 2
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	No   No   No   No	No No No		
Ceiling CleanYesWalls CleanYesFlooring CleanNoRoom Surfaces CleanNo	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes No	HVAC Return Grills Clean Inside of Return Duct Clean	No No
Trash RemovedYesSigns of PestsNoRoom ClutteredYes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes Yes N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly Yes Condensate Pan Clean Yes		Yes Yes	Mechanical Room Clean Inside of HVAC Unit Clean	Yes Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Outside of Room None	▼	Fresh Air Intake Free of Obstruction	Yes
Observations Ceiling tiles and light fixtures at HVAC Supply grills dirty - Dust on shelves and inside storage cabinets - Dirt / dust / debris on floor - Spotty microbial growth on underside of student tables - Papers / boxes/ plastic storage tubs on al counters, shelves and floor in room - Room to cluttered to clean properly.				

# Corrective Actions to be Completed by Site Based Staff

Thoroughly clean ALL surfaces	▼
Clean underside of tables with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Clean light fixtures around HVAC supply grills	▼
Encourage occupant to reduce clutter	▼
	▼
	▼
	▼

## **Corrective Actions to be Completed by PPO**

Evaluate and repair HVAC system as needed	Evaluate and repair HVAC system as needed
Check all controls / dampers / interlocks	Check all controls / dampers / interlocks
▼	
V	
V	
V	
▼	
▼	

	IAQ Assessr	nent		
Park Trails	Elementary Evaluation Dat	e January 13, 2016	Time of Day 11:	30 AM
Outdoor Conditions Temper	ature 70.4 Relative	Humidity 53.4	Ambient CO2 4	16
		Range CO <sup>2</sup> % - 60% 470	Range # O MAX 700 > Ambient	ccupants 3
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling2' X 4' Lay inWallsDrywallFloor12" x 12" Vinyl	No   No   No   No	No No		
Ceiling CleanYesWalls CleanYesFlooring CleanNoRoom Surfaces CleanNo	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes No	HVAC Return Grills Clean Inside of Return Duct Clean	No No
Trash RemovedYesSigns of PestsNoRoom ClutteredYes	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes Yes N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No
Mechanical Equipment Location Filters Installed Properly Yes Condensate Pan Clean Yes		Yes	Mechanical Room Clean nside of HVAC Unit Clean	Yes Yes
Fresh Air Intake Location Pollutant Sources Near Air Intake	Outside of Room None	▼	Fresh Air Intake Free of Obstruction	Yes
debris on floor - Spotty microbi	t HVAC Supply grills dirty - Dust al growth on underside of stude oom - Room to cluttered to clea	ent tables - Papers / box		

### Corrective Actions to be Completed by Site Based Staff

· · ·	
Thoroughly clean ALL surfaces	▼
Clean underside of tables with Wexcide	▼
Clean ceilings around HVAC supply grills	▼
Clean light fixtures around HVAC supply grills	▼
Encourage occupant to reduce clutter	▼
	▼
	▼
	▼

## **Corrective Actions to be Completed by PPO**

	_
Evaluate and repair HVAC system as needed	▼
Check all controls / dampers / interlocks	▼
Set Temperature to 72 - 78 degrees	▼
	▼
	▼
	▼
	▼
	▼