

Temp 64.8 RH 45.6 CO2 429

<b>FISH</b>	<b>Answer</b>	<b>Recommendation</b>
101F	Sever water damage on wall under A/C unit.	Physical Plant Operations to evaluate and repair as appropriate.
110	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
141	Signs of water intrusion. Leak identified - sink faucet.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
147	Signs of water intrusion. Leak identified - sink faucet.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
160	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
166	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
170	Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
802C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
803C	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. <b>Work order TS00593 generated by PPO.</b>
	Elevated moisture content in wall under A/C unit.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. <b>Work order TS00593 generated by PPO.</b>
	Dust and debris on A/C coils	Physical Plant Operation to evaluate and clean A/C coils. <b>Work order TS00594 generated by PPO.</b>