

# Tools for Schools - Indoor Air Quality

## Follow-up Action Plan for Project Manager



Riverside Elementary

77.6 71% 337

**Principal:** Mr. Larry Katz

**Walkthrough Date:** 4/28/2004

Temp RH Co2  
**Outside Measurements**

**Assignment Member:** Jeff Moquin

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
401	1	Project Manager	Moisture stained ceiling tile observed in bathroom vestibule. Further inspection revealed stain was dry.	Location will contact project manager to have roof inspected for leak, and to replace stained tile. Monitor for further stains.