Silver Lakes Elementary

Outdoor Parameter Measurements:

Temp

RH

Co2

WalkthroughDate: 5/21/2004

87 57%

	Category	Detail	Assessment Comments	Recommended Corrective Action
101	79 <i>Temp</i>	RH Co2		
	1 етр	KII C02		
	Health and Hygiene Education	Inform students and staff about the importance of good hygiene in preventing the spread of airborne contagious diseases.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Health and Hygiene Education	Provide information about IAQ and health.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Health and Hygiene Education	Establish an information and counseling program regarding smoking.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Health Officer's Office	Ensure that the ventilation system is properly operating.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Maintain Student Health Records	Include information about sensitivities to IAQ problems in student health records.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Maintain Student Health Records	Track health-related complaints by students and staff.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
	Maintain Student Health Records	Recognize indicators that health problems may be IAQ-related.	Teacher indicated she identified these items inadvertently. No problems were identified at time of inspection.	No corrective action recommended at this time.
10.15				
101G	77	41%		
	Temp	RH Co2		
	General Cleanliness	Clean spills promptly.	No spills were detected at time of assessment.	No corrective action recommended at this time.
	General Cleanliness	Check for pests.	At time of assessment, no pests were found.	No corrective action recommended at this time.

Friday, August 19, 2005 Page 1 of 9

-	Category	Detail	Assessment Comments	Recommended Corrective Action
101J	General Cleanliness	Confirm that the office area is cleaned properly 43%	Carpet clean, dust accumulation was observed on environmental surfaces.	Custodial staff should thorougly clean all environmental surfaces within classroom.
	Temp	RH Co2		
	Thermal Comfort	Check comfort factors.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
101Q	74 <i>Temp</i>	43% Co2		
	General Cleanliness	Check for pests.	At time of assessment, no pests were found	No corrective action recommended at this time.
	General Cleanliness	Confirm that the classroom is cleaned properly	Carpet clean, dust accumulation was observed on environmental surfaces.	Custodial staff should thorougly clean all environmental surfaces within classroom.
		Custodial does a wonderful job!!		
101R	76 <i>Temp</i>	RH Co2		
	Thermal Comfort	Check comfort factors.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.
101V	77 <i>Temp</i>	## Co2		

	Category	Detail	Assessment Comments	Recommended Corrective Action
	General Cleanliness	Check for pests.	At time of assessment, no pests were found.	No corrective action recommended at this time.
	General Cleanliness	Clean spills promptly.	Stain on carpet under refrigerator.	Clean and sanitize carpeting.
108	75	45%		
	Temp	RH Co2		
		The rear admin area needs addressing. It is an ac windows have leaked each year the floor level in a	Id-on with a vaulted ceiling and the heat in sill 4 offices. The A/C goes out whenever it ra	ummer is horrendous in the entire area. The ains hard.
129	76	47%		
	Temp	RH Co2		
	General Cleanliness	Confirm that the classroom is cleaned properly	Minor stains on floor tiles, surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces within classroom and floor tiles.
	Thermal Comfort	General items to watch for.	Teacher reported the room is generally warm. Temperature was within recommended range.	No corrective action recommended at this time.
	Ventilation	Determine how your classroom is ventilated.	2 return and 4 supply grills	No corrective action recommended at this time.
		The temperature in my room is not between 72 and	d 76 degrees.	
134	74	47%		
	Temp	RH Co2		
	Drain Traps in the Classroom	Drain traps, if present, can become a problem when the water in the drain trap evaporates due to infrequent use, allowing sewer gases to enter the room.	Trap was wet at time of assessment.	No corrective action recommended at this time.
	Industrial and Vocational Education Supplies	Learn about your supplies.	None found in room.	No corrective action recommended at this time.
	Thermal Comfort	General items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.

	Cat	egory		Detail	Assessment Comments	Recommended Corrective Action
	Thermal Comfo	ort	Humid	dity level.	The humidity was 47% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.
			It is freezing in	the classroom. There is no consist	ency. Either freezing cold or boiling because	A/C isn't working.
135		74	47%			
		Temp	RH	Co2		
	General Clean	liness	Confii prope	rm that the classroom is cleaned rly	Minor staining with dust and debris on floor tile. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces within classroom and clean and wax floor tile.
138		75	48%			
100		Temp	RH	Co2		
	General Clean		Check	c for pests.	At time of assessment, no pests were found. 2 ceiling tiles missing and HVAC return grill dirty.	No corrective action recommended at this time. Custodial staff to clean HVAC grills and replace missing ceiling tiles.
139		76	50%			
		Temp	RH	Co2		
	General Clean		Check	k for pests.	At time of assessment, no pests were found. Floor tile and HVAC return dirty, surfaces dusty.	No corrective action recommended at this time. Custodial staff should thorougly clean all environmental surfaces, floor tile and HVAC

	Cat	egory		Detail	Assessment Comments	Recommended Corrective Action
149		77	48%			
		Temp	RH	Co2		
	Drain Traps in	the Classroom	proble evapo	traps, if present, can become a em when the water in the drain trap orates due to infrequent use, ing sewer gases to enter the room.	Trap wet at time of assessment.	No corrective action recommended at this time.
	Excess Moistu	re in Classrooms		k for leaks or signs of moisture from ping or roofs.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	Excess Moistu	re in Classrooms	Cond	ensate (condensed water, or "fog") Id surfaces.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
	General Class	room Information			Standing water on counter at sink.	Custodial staff should clean spills promptly.
153		75	49%			
		Temp	RH	Co2		
	Art Supplies		Learr	about your supplies.	Only supplies found were school glue	No corrective action recommended at this
	General Clean	liness	Confi prope	rm that the classroom is cleaned	and glitter macaroni. Floor tile dirty and surfaces dusty.	time. Custodial staff should thorougly clean all environmental surfaces and floor tile within
	Thermal Comf	ort	Humi	dity level.	The humidity was 49% at the time of assessment. The desired humidity level is below 60%.	classroom. No corrective action recommended at this time.
160		75	50%			
		Temp	RH	Co2		
	General Clean	liness	Chec	k for pests.	At time of assessment, no pests found.	No corrective action recommended at this time.

201	Seneral Cleanliness 73 Temp General Cleanliness	49% <i>RH</i>	m that the classroom is cleaned rly Co2	Floor tile dirty and surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floor tile within classroom.
	Temp	RH	Co2		
G	General Cleanliness	2.			
		Clean	spills promptly.	Staining on floor tile.	Custodial staff should thorougly clean floor tile.
G	General Cleanliness	Confir proper	m that the classroom is cleaned rly	Floor tile dirty, surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floor tile within classroom.
V	rentilation	confirr	have mechanical ventilation, in that air is flowing into the room ne air supply vent(s).	Air is flowing into the room from the air supply vents.	No corrective action recommended at this time.
203	74	50%			
	Тетр	RH	Co2		
E	excess Moisture in Classrooms		for leaks or signs of moisture from ing or roofs.	1 stained ceiling tile.	Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
G	General Cleanliness	Confir proper	m that the classroom is cleaned rly	Floor tile stained and dirty, surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and clean and wax floor tile within classroom.
L	ocal Exhaust Fans	exhau	m that fume hoods and local st fans are used whenever es that generate pollutants take	Exhaust fan working at time of assessment.	No corrective action recommended at this time.
L	ocal Exhaust Fans		m that fume hoods and local st fans function properly.	There were no problems observed at time of assessment.	No corrective action recommended at this time.

	Category		Detail	Assessment Comments	Recommended Corrective Action
204	75	52%			
	Temp	RH	Co2		
	Animals in the Classroom	Gene	eral items to watch for.	No animals in the classroom.	No corrective action recommended at this time.
	Excess Moisture in Classrooms		densate (condensed water, or "fog") old surfaces.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
205	75	56%			
	Temp	RH	Co2		
	Excess Moisture in Classrooms		densate (condensed water, or "fog") old surfaces.	There were no problems observed at time of assessment.	No corrective action recommended at this time.
209	74	55%			
	Temp	RH	Co2		
	Excess Moisture in Classrooms	Cond	densate (condensed water, or "fog")	None found at time of assessment.	No corrective action recommended at this
	Excess Moisture in Classrooms	on co Chec	old surfaces. ck for leaks or signs of moisture from bing or roofs.	Stained ceiling tiles.	time. Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
	General Classroom Information			Stains on ceiling tiles and tiles dirty at supply grills.	Clean dirty ceiling tiles at supply grills and replace stained ceiling tiles.
	General Cleanliness	Conf prop	irm that the classroom is cleaned erly	Minor stains on floor tiles. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and clean all floor tiles within classroom.
	Thermal Comfort	Hum	idity level.	The humidity was 55% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.
	Thermal Comfort	Gene	eral items to watch for.	Temperature was within acceptable range at time of assessment.	No corrective action recommended at this time.

	Category	Detail	Assessment Comments	Recommended Corrective Action
	Ventilation	If you have mechanical ventilation, confirm that air is flowing from the room into the air return grille(s).	Return air grill is functioning properly.	No corrective action recommended at this time.
	Ventilation	If you have mechanical ventilation, confirm that air is flowing into the room from the air supply vent(s).	Air is flowing into the room from the air supply vents.	No corrective action recommended at this time.
	Ventilation	Check for unexplained odors.	No odors were detected at time of assessment.	No corrective action recommended at this time.
	Ventilation	Determine how your classroom is ventilated.	2 return and 4 supply grills.	No corrective action recommended at this time.
210	74 Temp	56% Co2		
	Thermal Comfort	Humidity level.	The humidity was 56% at the time of assessment. The desired humidity level is below 60%.	No corrective action recommended at this time.
	Thermal Comfort	General items to watch for.	Ceiling tiles dirty around HVAC supply grills.	Clean ceiling tiles around HVAC supply grills.
212	74	55%		
	Temp	RH Co2		
	Excess Moisture in Classrooms	Check for leaks or signs of moisture from plumbing or roofs.	Water stains under sink.	Maintenance to inspect for leak and repair as appropriate.
	Ventilation	Check for unexplained odors.	2 bags of wet potting soil and comet cleanser under sink at time of assessment.	Remove all organic material and non SBBC chemicals.

	Category	Detail	Assessment Comments	Recommended Corrective Action
214	76 <i>Temp</i>	8H Co2		
	General Cleanliness	Confirm that the classroom is cleaned properly	Minor staining, dust and dirt on floor tile. Surfaces dusty.	Custodial staff should thorougly clean all environmental surfaces and floor tile within classroom.
24	73 <i>Temp</i>	54% Co2		
	General Cleanliness	Check for pests.	At time of assessment no pests were found.	No corrective action recommended at this time.
32	General Cleanliness 73 Temp	Check for pests. 51% RH Co2		
32	73	51%		
32	73 <i>Temp</i>	51% Co2	At time of assessment no pests were found. Chocolate syrup, strawberry syrup, caramel syrup in cabinet and	time.