

managing risk with responsibility

se Only

ressed

Aston A. Henry, Director Risk Management Department		Telephone:754 321-1900Fax:754 321-1917
April 24, 2014	Signature on File	For Custodial Supervisor Use (
TO:	Saemone Hollingsworth, Principal Silver Ridge Elementary School	Custodial Issues Addressed
FROM:	Richard Rosa, Project Manager Risk Management Department	

SUBJECT: Indoor Air Quality (IAQ) Assessment

On March 19, 2014, I conducted an assessment at Silver Ridge Elementary School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction cc: Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RR/tc Enc.

IAQ Assessment								
Silver Rid	dge Elementary Evaluation Dat	te March 19, 2014	Time of Day	2:00				
Outdoor Conditions Tem	perature 85.4 Relative	e Humidity 42.8	Ambient CO2	415				
FishTemperatureP-1201VE72.5		Range CO ² % - 60% 1258		2				
Noticeable Odor Yes Ceiling painted wood	Visible water damage / staining?	Visible microbial growth? Yes	Amount of material affected >15 stains					
Ceiling painted wood Walls Paneling/tackboar	rd <u>No</u>	No						
Floor Rugs / 12"x12"	Yes	No	4 sq ft					
Ceiling CleanNoWalls CleanYesFlooring CleanYesRoom Surfaces CleanNo	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	No Yes No	HVAC Return Grills Clean Inside of Return Duct Clean					
Trash RemovedYesSigns of PestsYesRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	Yes N/A N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No				
	on Bard like HVAC system in clas N/A Filters Clean N/A Cooling Coil Clean		Mechanical Room Clean Inside of HVAC Unit Clean	N/A N/A				
Fresh Air Intake Location Pollutant Sources Near Air Intake	Behind Bard unit/Exterior wal Grass and landscape	II ▼ ▼	Fresh Air Intake Free of Obstruction	Yes				

Observations

Recommend that a roofer evaluate the roofing, various stains in ceiling. Recommend that the HVAC dept. repair the HVAC system, supply vents are sweating and staining the ceiling, exterior doors are not left open. Possible insulation breech on HVAC duct work. The instructor has stated the HVAC unit comes on at times blowing wet air into the room. The restroom is out of order due to a hole in the floor. Check for water intrusion, possible irrigation sprinkler under portable. Repair replace the flooring in the restroom. Insects were observed in restroom, due to breech in floor.

Corrective Actions to be Completed by Site Based Staff

evated surfaces	Thoroughly clean e
rills with Wexcide	Clean HVAC supply g
AC return grill ▼	Vacuum/wipe HV
•	
▼	
▼	
▼	
▼	

Corrective Actions to be Completed by PPO

Evaluate and repair cause of stained ceiling tiles		
Repair HVAC to reduce CO2 levels		
Repair stained ceiling adjacent to the supply vents	▼	
Remove and replace stained ceiling tiles	▼	
Evaluate and repair HVAC duct insulation	▼	
Repair/replace flooring in restroom	▼	
	▼	
See Observations for additional information	▼	