## **Tools for Schools - Indoor Air Quality**

## **Follow-up Action Plan for Site**

West Hollywood Elementary 83 57% Principal: Mr. Dennis Sciullo

Walkthrough Date: 5/27/2004 Temp RH Co2 Assignment Member: Bob Krickovich

**Outside Measurements** 



Room	Priority	Responsible	Assessment Comments	<b>Recommended Corrective Action</b>
129	2	Site	Dust accumulation was observed on environmental surfaces. Flooring dirty.	Custodial staff should thorougly clean all environmental surfaces within classroom and clean and wax flooring.
204	2	Site	Carpeting is stained.	Remove carpet and install new tile floor.
205	3	Site		Site based administration will provide information to site based staff.
205	3	Site		Contact EPA website www.epa.gov/iaq
205	3	Site		Site based administration will provide information to site based staff.
205	3	Site		Site based administration will provide information to site based staff.
205	3	Site		Site based administration will provide information to site based staff.
205	3	Site		Site based administration will provide information to site based staff.
205	3	Site		Site based administration will provide information to site based staff.
317	3	Site	Flooring needs to be cleaned and waxed. Too much is stored in the room to properly clean the floor.	Clean and wax flooring. Remove some of the stored items.
402	3	Site	Carpeting is slightly stained.	Clean and sanitize carpeting.
622P	3	Site	Condensation on fixtures in front of A/C units.	Redirect air flow from HVAC so that it does not blow directly on fixtures.

8/19/2005 West Hollywood Elementary Sorted by Room and Priority Page 1 of 1