

managing risk with responsibility

Aston A. Henry, Supervisor Telephone: 754 321-1900 Risk Management Department Fax: 754 321-1917

January 25, 2013

Signature on File

TO: Wendy Doll, Principal

Cooper City High School

FROM: Richard Rosa, Project Manager

Facilities Design and Construction

SUBJECT: Indoor Air Quality (IAQ) Assessment

For Custodial Supervisor Use Only		
	Custodial Issues Addressed	
	Custodial Issues Not Addressed	
-		

On January 22, 2013, I conducted an assessment at **Cooper City High School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Directors, School Performance & Accountability
Shelley Meloni, Executive Director, Facilities Design and Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Supervisor, Risk Management
Sonja Coley, Senior Project Manager, Facilities Design and Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Cooper City High Evaluation Date January 22	2013 Time of Day 1:15				
Outdoor Conditions Temperature 78.9 Relative Humidity	51.4 Ambient CO2 417				
Fish Temperature Range Relative Humidity Range 141 73.9 72 - 78 56.2 30% - 60%	CO² Range # Occupants 1478 MAX 700 > 18 Ambient 18				
Noticeable Odor No Visible water damage / Staining? Visible micro growth?	bial Amount of material affected				
Ceiling 2' x 4' No No					
Walls Vinyl paneling No No					
Floor 12" x 12" Vinyl No No					
Ceiling Clean Yes HVAC Supply Grills Clean Yes	HVAC Return Grills Clean Yes				
Flooring Clean Yes Inside of Supply Duct Clean Yes	Inside of Return Duct Clean Yes				
Room Surfaces No Ceiling at Supply Grills Clean Yes					
Trash Removed Yes Exhaust Fans Working N/A	Unapproved Chemicals / Cleaners in Room				
Signs of Pests No Drain Traps Wet N/A					
Room Cluttered No Food if Stored in Room is in Sealed Containers N/A	Air Fresheners No in Room				
Mechanical Equipment Location Roof Top AHU # 1	Mechanical Room Clean N/A				
Filters Installed Properly Yes Filters Clean Yes	Inside of HVAC Unit Clean No				
Condensate Pan Clean No Cooling Coil Clean No					
Fresh Air Intake Location Roof top	▼ Fresh Air Intake Free				
Pollutant Sources Near Air Intake	of Obstruction				
Observations					
F-141 or school # 114 Evaluate HVAC coil for clean. Visible microbial growth inside HVAC unit. Large gap on the hinged side of the exterior door. CO2 level slightly elevated.					
Corrective Actions to be Completed by Site Based Staff Corrective	e Actions to be Completed by PPO				

composite and completed by the Eucon claim		
Thoroughly clean elevated surfaces	▼	
	▼	
	▼	
	▼	
	▼	
	▼	
	▼	
	▼	

Corrective Actions to be completed by 110		
Repair HVAC to reduce CO2 levels		
Evaluate & replace exterior door weather stripping		
Evaluate HVAC coil for cleaning	▼	
Clean microbial growth from inside HVAC unit	▼	
Clean condensate pan	•	
	▼	
	▼	
	▼	