## THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

## **TELEPHONE (754) 321-4200**

FACSIMILE: (754) 321-4285

December	11, 2015	Signature on File	For Custodial Supervisor Use Only
TO:	Anthony V <b>Northeast I</b>	alachovic, Principal <b>High</b>	Custodial Issues Addressed
FROM:		er, Project Manager ntal Health & Safety Department	Custodial Issues Not Addressed
SUBJECT:	Indoor Air Qua	lity (IAQ) Assessment	

On December 8, 2015, I conducted an assessment at **Northeast High School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

cc: Shelley Meloni, Director, Pre-Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Broward Teachers Union Federation of Public Employees Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Rich Volipi, Supervisor II Custodial Mark Murray, Supervisor II Custodial Sam Bays, Director, Maintenance Operations Kurt Wirz, Area Manager Trades

IAQ Assessment								
	Northeast	t High Evaluation Da	te December 8, 201	5 Time of Day 11:0	00 A.M.			
Outdoor Conditions	Temperature	72.8 Relative	e Humidity 97.5	Ambient CO2 5	75			
Fish Temperation   212 66.1		Relative Humidity87.430	<b>Range Co</b> % - 60% 89		ccupants 2			
Noticeable Odor	Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected				
Ceiling Tectu	um	No						
Walls Ecoustic par	nel/plaster	Yes	No	Area by 212E				
Floor Carp	et	Yes	No	Area by 212E				
	Yes No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No			
	No	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	Yes			
Room Surfaces	No	Ceiling at Supply Grills Clean	N/a					
Trash Removed	No	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No			
Signs of Pests	No	Drain Traps Wet	N/A					
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No			
Mechanical Equipment Location FISH #219 Mechanical Room Clean								
Filters Installed Properl	у 🗌	Filters Clean		Inside of HVAC Unit Clean				
Condensate Pan Cle	an 🦳	Cooling Coil Clean						
Fresh Air Intake Locatic Pollutant Sources Near Intake		accessible	▼ ▼	Fresh Air Intake Free of Obstruction				
Observations								
Band Room - roof leak in the area around 212E. Temperature and humidity issues. Water damaged door. Microbial growth on wall in closet 212E. Remove contents and clean. Sound panels need to be cleaned. Supply and return grills								
growth on wait in closer 212E. Remove contents and clean. Sound panels need to be cleaned. Supply and return grins								

need to be cleaned. A/C equipment not accessible - ladder to loft was not secure. Carpet needs to be evaluated for replacement or professional cleaned. Classroom needs to be cleaned thoroughly.

Corrective Actions to be Completed by Site Based Staff

Clean dust and debris from sound panels				
Thoroughly Clean Classroom	▼			
Remove items in 212E and clean with wexcide	▼			
Clean Supply Grills with Wexcide	▼			
Vacuum return grill	▼			
	▼			
	▼			
	▼			

Corrective Actions to be Completed by PPO

Set Temperature to 72 - 78 degrees				
Repair HVAC to Reduce Humidity Levels				
Evaluate cause of water damage and repair/replace				
Evaluate the need for carpet replacement	▼			
Repair/replace water damaged door				
Secure ladder in 212E	▼			
Remove water damaged wall and replace	▼			
	▼			