

Aston A. Henry, Task Assigned Director

# managing risk with responsibility

754 321-1900

Telephone:

Risk Management Department		Fax:	754 321-1917
April 22, 2013	Signature on File	For Custodial Supervisor Use Only	
TO:	John LaCasse, Principal Nova High School		ues Addressed ues Not Addressed
FROM:	Richard Rosa, Project Manager Facilities Design and Construction		-
SUBJECT	Indoor Air Quality (IAO) Assessment		<u> </u>

On March 21, 2013, I conducted an assessment at **Nova High School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Directors, School Performance & Accountability
Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Task Assigned Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities Design and Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

### **IAQ Assessment**

	Nova High Evaluation Date	te March 21, 2013	Time of Day1	1:45
Outdoor Conditions Temper	rature 73.0 Relative	Humidity 32.1	Ambient CO2 4	04
		Range <u>CO</u> <sup>2</sup> % - <b>60</b> %		32
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' x 4'	No	No		
Walls Drywall	No	No		
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean No Walls Clean Yes	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	Yes
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes
Room Surfaces No Clean	Ceiling at Supply Grills Clean	No		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A		
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location	FISH 284A		Mechanical Room Clean	Yes
Filters Installed Properly N/	A Filters Clean	N/A	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean N/	Cooling Coil Clean	N/A		
Fresh Air Intake Location	Thru exterior wall	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake	No	▼	of Obstruction	
Observations				

There was no odor at the time of assessment but the instructor states there are odors in the morning especially on Monday mornings. There is a display of artifacts that remain dusty, too cluttered to clean properly. The HVAC filters were protruding from the unit. One filter door is completely rusted shut, evaluate for repair. In the mechanical room, repair replace West wall for water damage caused by a leaking chilled water pipe. Check the opposite side wallboard for water damage when the mechanical room side is open, and repair or replace as necessary.

## Corrective Actions to be Completed by Site Based Staff

Otan
▼
▼
▼
▼
•
•
▼
▼

### Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼	
Remove/replace water damaged west wall	▼	
Evaluate the cleaning of the HVAC coil	▼	
Repair leaking chilled water pipe and re-insulate		
	▼	
	▼	
	▼	
	▼	