## THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

**TELEPHONE (754) 321-4200** 

February 10, 2017		nature on File	For Custodial Supervisor Use Only	
TO:	Olayemi Awofadeju, Pri			Custodial Issues Addressed
	South Broward High	yh .		Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Pro Environmental Health &			
SUBJECT:	Indoor Air Quality (IAQ	) Assessment		

On February 9, 2017, I conducted an assessment at South Broward High School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

Shelley Meloni, Director, Pre-Construction cc: Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division

> **Broward Teachers Union** Federation of Public Employees Gerald Devio, Supervisor II Custodial Benjamin Osborne, Supervisor II Custodial Mark Murray, Supervisor II Custodial Sam Bays, Director, Maintenance Operations

Kurt Wirz, Area Manager Trades

## **IAQ Assessment**

South Browar	d High Evaluation Da	February 9, 2017	Time of Day 1:	15					
Outdoor Conditions Temperature	88.8 Relativ	ve Humidity 48.3	Ambient CO2 45	8					
Fish         Temperature         Range           620         73.8         72 - 78	Relative Humidity 64.6 3	Range CO <sup>2</sup> 0% - 60%	Range # Occ MAX 700 > Ambient	30					
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected						
Ceiling 2' X 4' Lay in	Yes	No	4 ceiling panels						
Walls Plaster	No	No							
Floor 12" x 12" Vinyl	No	No							
Ceiling Clean Yes Walls Clean No Flooring Clean No	HVAC Supply Grills Clean Inside of Supply Duct Clean	Yes	HVAC Return Grills Clean Inside of Return Duct Clean	No No					
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes							
Trash Removed Yes  Signs of Pests No	Exhaust Fans Working  Drain Traps Wet	N/A	Unapproved Chemicals / Cleaners in Room	N/A					
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers		Air Fresheners in Room	No					
Mechanical Equipment Location FISH 623A Mechanical Room Clean Yes									
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes					
Condensate Pan Clean Yes Cooling Coil Clean Yes									
Fresh Air Intake Location  Pollutant Sources Near Air Intake	u exterior wall	<b>▼</b>	Fresh Air Intake Free of Obstruction	Yes					
Observations									
Occupant reports headaches and "stuffy" feeling.  Motor on fresh air damper does not function.									
Corrective Actions to be Completed by Site Based Staff  Corrective Actions to be Completed by PPO									
Remove and replace stained ceiling tile ▼ Repair HVAC to Reduce CO2 Levels									
If stains return, contact COMPASS for work order ▼ Evaluate fresh air damper at HVAC									
Clean dust buildup on horizontal/elevated surfaces   Clean corners on floor, minor dirt buildup  Clean corners on floor, minor dirt buildup  Repair HVAC to Reduce Humidity Levels									
Clean corners on noor, minor and sunday									