ATTUCKS MIDDLE

Walkthrough Date: 03/30/2007 Temp RH CO2
Outdoor Parameters: 75.7 55.1 493

to monitor condition and initiate a work order for

	a				
Room	Section	Question	Answer	Recommendation	Responsible
230	Inside Parameters:	Temp	RH	CO2	
		71.0	55.5	641	
	GENERAL	Floor is cleaned on a regular	Floor was clean at the time		
	CLEANLINESS	basis?	of assessment.		
Room	Section	Question	Answer	Recommendation	Responsible
234	Inside Parameters:	Тетр	RH	CO2	
ii ii	Ï	67.8	59.0	620	İ
	THERMAL COMFORT	Temperature in my classroom is generally comfortable (72F- 76F)?	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.	Site
	LOCAL EXHAUST FANS	Other exhaust fans that may exist in the classroom are functioning properly?	No exhaust fans in room. Identified in error.		
Room	Section	Question	Answer	Recommendation	Responsible
248	Inside Parameters:	Тетр	RH	CO2	
Ï Ï	Ï	70.0	54.4	687	
	GENERAL CLEANLINESS EXCESS MOISTURE IN	Room is free of pests? Ceiling tiles or walls free of leaks and/or discoloration	of assessment.	Work order already generated by Physical Plant Operations for pest concerns.	
	CLASSROOMS	(discoloration may indicate periodic leaks)?			1
Room	Section	Question	Answer	Recommendation	Responsible
290	Inside Parameters:	Тетр	RH	CO2	
		67.7	62.5	647	
	THERMAL COMFORT	Temperature in my classroom is generally	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue	Site

comfortable (72F- 76F)?

Site

Physical Plant Operations to evaluate the HVAC

serviceperson staff to adjust the thermostat. Continue

to monitor condition and initiate a work order for

Site based administration to encourage facility

system if temperature does not improve.

				Physical Plant Operations to evaluate the HVAC system if temperature does not improve.	
Room	Section	Question	Answer	Recommendation	Responsible
304	Inside Parameters:	Temp	RH	CO2	
		68.2	60.2	691	
		Water poured down floor drains once per week (approx. 1 quart of water).	Water is not poured down floor drain at least once a week.	Site based administration should address maintenance of sinks toilets and drains with facility serviceperson staff.	Site
	EXCESS MOISTURE IN CLASSROOMS	Classroom lavatories/water fountains free of leaks?	No leaks or signs of water intrusion identified. Room is a science classroom and sink is being utilized as a file	Ensure that water is run in sinks at least once a week.	Site

Temperature was low at the

time of assessment.

cabinet.

Classroom is free of

shifts?

significant temperature

THERMAL

COMFORT