

Aston A. Henry, Director
Risk Management Department

Telephone: 754 321-1900
Fax: 754 321-1917

December 12, 2013

Signature on File

TO: James McDermott, Principal
Bair Middle School

FROM: Robert Krickovich, Coordinator I, LEA
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed
<hr/>	
<hr/>	

On December 5, 2013, I conducted an assessment at **Bair Middle School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RK/tc
Enc.

IAQ Assessment

Bair Middle

Evaluation Date December 5, 2013

Time of Day 10:30

Outdoor Conditions Temperature 83.3

Relative Humidity 63.0

Ambient CO2 536

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
121C	68.5	72 - 78	59.7	30% - 60%	1013	MAX 700 > Ambient	2
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' X 4' Lay in		No		No		
Walls	Drywall		No		No		
Floor	Carpet		Yes		Yes		120 Sq Ft water Damaged

Ceiling Clean	Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	Yes
Walls Clean	Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes
Flooring Clean	Yes	Ceiling at Supply Grills Clean	Yes		
Room Surfaces Clean	Yes				

Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A		

Mechanical Equipment Location	FISH 125		Mechanical Room Clean	Yes	
Filters Installed Properly	Yes	Filters Clean	No	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean	No	Cooling Coil Clean	No		

Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	None ▼		

Observations

Carpet stained / wet at dark edges in front of room 121A - most likely from water coming up from slab - Possible microbial growth in dark spots on carpet

Corrective Actions to be Completed by Site Based Staff

Remove and replace A/C filters	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Remove carpet in 121C and replace with tile	▼
Evaluate and repair cause of water intrusion	▼
Clean HVAC coil in FISH 125 and 106	▼
Clean pan in FISH 125 and pitch to drain	▼
	▼
	▼
	▼
	▼