

Jeffrey S. Moquin, Director
Risk Management Department

Telephone: 754-321-3200
Facsimile: 754-321-3290

July 12, 2005

TO: Ms. Victoria Kaufman, Principal
Coral Springs Middle School

FROM: Aston A. Henry, Jr., Supervisor
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment
FISH 111

On June 30, 2005 the IAQ Assessment Team conducted an assessment of FISH 111 at **Coral Springs Middle School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent
Craig Anderson, Area Director
Jeffrey S. Moquin, Director, Risk Management
Paul H. Bach, Project Manager II, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Project Manager II, Facilities and Construction Management

AAH/tc
Enc.

IAQ Assessment

Coral Springs Middle School

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions Temperature Relative Humidity Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="111"/>	<input type="text" value="71.1"/>	<input type="text" value="72 - 78"/>	<input type="text" value="58.8"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="473"/>	<input type="text" value="Max 700 > Ambient"/>	<input type="text" value="2"/>
Noticeable Odor	<input type="text" value="No"/>		Visible water damage / staining?	Visible microbial growth?	Amount of material affected		
Ceiling Type	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Wall Type	<input type="text" value="Drywall"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Flooring	<input type="text" value="Carpet"/>		<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="Some Areas"/>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Flooring	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean and sanitize"/>
HVAC Supply Grills	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean with Wexcide disinfectant"/>
HVAC Return Grills	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean with Wexcide disinfectant"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

Observations

Findings:

- No visible signs of microbial growth
- The entire room appears clean with the exception of carpet
- Carpet reveals signs of staining in some areas
- Dust and debris on HVAC supply and return grills

Recommendations:

Site Based Maintenance:

- Clean and sanitize carpet throughout the entire media center. If complaint continues call for re-evaluation.
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate