

# Tools for Schools - Indoor Air Quality

## Follow-up Action Plan for District Maintenance



Crystal Lake Middle

**Principal:** Mr. James Neer

**Walkthrough Date:** 4/16/2004

Temp    RH    Co2  
**Outside Measurements**

**Assignment Member:** Mark Dorsett

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
1101CS	2	District Maintenance	Portable interior wall is damaged.	Replace wall.
122	2	District Maintenance		Install transfer grill.
122	2	District Maintenance	Carpeting is stained and rippling.	Replace carpeting.
149	1	District Maintenance	Ceiling tiles are wet.	Maintenance to inspect for leak and repair as appropriate and replace ceiling tiles.
153	1	District Maintenance	Ceiling tiles are stained.	Maintenance to inspect for leak and repair as appropriate and replace ceiling tiles.
204	1	District Maintenance	Stained ceiling tiles.	Maintenance to inspect for leak and repair as appropriate and replace ceiling tiles.
208	1	District Maintenance	Stained ceiling tiles.	Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
Site	2	District Maintenance		Evaluate motorized dampers through the entire school.