

# managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

September 10	, 2007	Signature on File	
TO:	Mr. Frank Zag <b>Indian Ridge</b>	ari, Principal <b>Middle School</b>	
FROM:		roject Manager nent Department	
SUBJECT:	Indoor Air Qu <b>FISH 104</b>	ality (IAQ) Assessment	

On September 6, 2007 I conducted an assessment FISH 104 at **Indian Ridge Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent Margaret Underhill, Area Director Jeffrey S. Moquin, Director, Risk Management James Carballo, Project Manager, Facilities and Construction Management Ralph Eckhardt, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ Ass	sessment	Location N	lumber	3471	
Indian Ridge Middle School					Evaluation	Requested	Septemb	oer 4, 2007
Time of Day	3:00 pm				Eval	uation Date	Septemb	oer 6, 2007
Outdoor Cond	itions Tem	perature 8	9.1	Relative Humidity	56.7	Ambie	nt CO2	460
Fish	Temperature F	ange Relat	ive Humidity	Range	CO2	Ran	nge #	Occupants
104	75.3 <b>7</b> 2	2 - 78	43	30% - 60%	1184	Max 700	> Ambient	3
Noticeable Oc	lor No		isible water age / staining	Visible micro ? growth?		nount of ma affected	terial	
Ceiling Type	2 x 4 Lay	n	No	No			None	
Wall Type	Drywall		No	No			None	
Flooring	Vinyl		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	e Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Νο	Yes	Yes		Clean	and sanitiz	ze	
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clean a	as appropri	ate	

## Observations

#### Findings:

- Environmental parameters were acceptable

- Dust and debris on floor between teachers' desk and window

- Dust build up on top shelf and counter

#### -Recommendations:

### Site Based Maintenance:

- Clean and sanitize floor

- Clean top shelf and counter

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate