

Tools for Schools Phase II - Indoor Air Quality

Follow-up Action Plan for Site Based



New River Middle

0881

86.1 63.2 497

Principal: Mr. Jan Beal

Walkthrough Date: 5/16/2005

Temp RH Co2
Outside Measurements

Room	Priority	Responsible	Response	Recommendation
115	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
115	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
126	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
174	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
175	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
175	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
179	2	Site Based	Carpet was stained.	Site based administration should address general cleanliness with facility serviceperson staff.
179	2	Site Based	Dust observed on supply/return registers at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
181	2	Site Based	Missing A/C grill	Facilities serviceperson to replace missing grill
183	2	Site Based	Dust observed on supply/return registers at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
304	2	Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
304	2	Site Based	Dust observed on supply/return registers at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.

Room	Priority	Responsible	Response	Recommendation
304	2	Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
304	2	Site Based	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
304	2	Site Based	Dust and dirt accumulation on floor.	Site based administration should address general cleanliness with facility serviceperson staff.
304	3	Site Based	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
304B	2	Site Based	Dust observed on supply/return registers at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
304B	2	Site Based	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
304B	2	Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
304B	2	Site Based	Dust and dirt accumulation on floor.	Site based administration should address general cleanliness with facility serviceperson staff.
304B	2	Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
304B	2	Site Based	There appears to be a problem with spill clean up practices. To address all spills in a timely manner, all moisture effected materials must be dried within a 24-hour timeframe.	Site based administration should address general cleanliness with facility serviceperson staff.
304B	2	Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
92C		Site Based	Temperature was low at the time of assessment.	Facilities serviceperson should monitor this room.
92C	2	Site Based	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
92C	2	Site Based	Dust observed on supply/return registers at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.