

Temp 71.7 RH 46.1 CO2 598

| FISH | Answer | Recommendation |
|-----------------|---|---|
| 002 Near 136 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| 101 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| | Gaps in windows identified at the time of assessment. | Physical Plant Operations to evaluate and repair as appropriate. |
| 108 | Missing broken or damaged floor tiles. | Physical Plant Operations to evaluate and repair/replace as appropriate. |
| 110 | Carpet was stained torn rippled or buckled. | Physical Plant Operations to evaluate and repair/replace as appropriate. |
| | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| 126 | Humidity was slightly elevated at the time of assessment. | Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level. |
| 128 | Humidity was slightly elevated at the time of assessment. | Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level. |
| 130 | Humidity was slightly elevated at the time of assessment. | Physical Plant Operations to evaluate HVAC system for proper operation and repair as appropriate to lower humidity level. |
| 134 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| 137 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| 138 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| 139 | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |
| | Hole in wall and gap in light fixture. | Physical Plant Operations to evaluate and repair as appropriate. |
| 149A | Signs of water intrusion. Stained ceiling tiles. | Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate. |