Beachside Montessori Village IAQ Walkthrough 5/2/2012

2041

Outside Temp 79.3 RH% 77.4 CO2 467

FISH/Roo	m Concern	Findings	Recommendation	Responsible Priority
101R	Temp 7	2.7 RH% 54.1 CO2 580		_
	Room is usually comfortable? (If no, please explain in the notes below.)	No issues were identified at the time of the assessment.	None at this time.	
	Temperature in my classroom is generally comfortable (72F-78F)?	No issues were identified at the time of the assessment.	None at this time.	
103A	Temp	3.2 RH% 53.3 CO2 574		
	Art supplies okay?	Identified in error. Does not apply. Media Office	Identified in error.	
	Exposure minimized for art supplies?	Identified in error. Does not apply.	Identified in error.	
	Exposure minimized for industrial supplies?	Identified in error. Does not apply.	Identified in error.	
	Exposure minimized for science supplies?	Identified in error. Does not apply.	Identified in error.	
	Following good handling and storage practices for art supplies?	Identified in error. Does not apply.	Identified in error.	
	Following good handling and storage practices for industrial supplies?	Identified in error. Does not apply.	Identified in error.	
	Following good handling and storage practices for science supplies?	Identified in error. Does not apply.	Identified in error.	

Beachside Montessori Village Page 1 of 7

FISH/Room	m Concern	Findings	Recommendation	Responsible	Priority
103A	Тетр	73.2 RH% 53.3 CO2 574			
	Industrial supplies okay?	Identified in error. Does not apply.	Identified in error.		
	Science supplies okay?	Identified in error. Does not apply.	Identified in error.		
	Temperature in my classroom is generally comfortable (72F-78F)?	No issues were identified at the time of the assessment.	None at this time.		
109	Тетр	70.9 RH% 64.8 CO2 597			
	Classroom is dusted/vacuumed thoroughly and regularly?	General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	Classroom is free of significant temperature shifts?	Temperature was not within range at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
	Humidity is generally acceptable? (Typically too high if higher than 60% relative humidity [RH] or too low if lower than 30% RH.)	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
		South Area working on ongoing A/C issues			
	Indoor surfaces of exterior walls free of continuous condensation?	Environmental parameters were not within acceptable range at the time of the assessment.	See previous recommendation.		
	Other exhaust fans that may exist in the classroom are functioning properly?	No issues were identified at the time of the assessment.	None at this time.		
	Room is free of smell of kitchen/food?	No issues were identified at the time of the assessment.	None at this time.		
	Room is usually comfortable? (If no, please explain in the notes below.)	Environmental parameters were not within acceptable range at the time of the assessment.	See previous recommendation.		

Beachside Montessori Village Page 2 of 7

FISH/Room	m Concern	Findings	Recommendation	Responsible	Priority
109	Temp	70.9 RH% 64.8 CO2 597	C		
	Temperature in my classroom is generally comfortable (72F-78F)?	Environmental parameters were not within acceptable range at the time of the assessment.	See previous recommendation.		
118	Тетр	71.7 RH% 58.2 CO2 638			
	Air supply/return registers are cleaned regularly and free of dust and debris accumulation?	Dust and debris on HVAC supply and/or return grills.	Clean HVAC supply and/or return grills with District approved germicical cleaner	Site	2
129	Temp	71.3 RH% 62.5 CO2 650			
	Air supply/return registers are cleaned regularly and free of dust and debris accumulation?	No issues were identified at the time of the assessment.	None at this time.		
	Classroom is dusted/vacuumed thoroughly and regularly?	General cleanliness Issues were identified at the time of the assessment due to excessive clutter in the room.	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc. Site based administration to encourage occupant to reduce clutter to assist with cleaning efforts.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
134	Temp	73.7 RH% 65 CO2 713			
	Floor is cleaned on a regular basis?	No issues were identified at the time of the assessment. Previous issues with flooring.	None at this time.		
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
155	Temp	73.3 RH% 70.1 CO2 724			
	Classroom is dusted/vacuumed thoroughly and regularly?	General cleanliness Issues were identified at the time of the assessment due to excessive clutter in the room.	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc. Site based administration to encourage occupant to reduce clutter to assist with cleaning efforts.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2

Beachside Montessori Village Page 3 of 7

FISH/Roo	m Concern	Findings	Recommendation	Responsible	Priority
155	Temp X - Plants	73.3 RH% 70.1 CO2 724 Live plants in room.	Remove live plants from room. Soil is a source of microbial growth.	Site	2
159	Temp Classroom is dusted/vacuumed thoroughly and regularly?	72.7 RH% 70.5 CO2 721 General cleanliness Issues were identified at the time of the assessment due to excessive clutter in the room.	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc. Site based administration to encourage occupant to reduce clutter to assist with cleaning efforts.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
202	Temp Air supply/return registers are cleaned regularly and free of dust and debris accumulation?	73.2 RH% 76.3 CO2 933 No issues were identified at the time of the assessment.	None at this time.		
	Classroom is dusted/vacuumed thoroughly and regularly?	General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
208	Temp Classroom is dusted/vacuumed thoroughly and regularly?	73.5 RH% 71.3 CO2 847 No issues were identified at the time of the assessment. Occupant indicated room recently cleaned.	None at this time.		
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
210	Temp Classroom is dusted/vacuumed thoroughly and regularly?	74 RH% 67.2 CO2 955 General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2

Beachside Montessori Village Page 4 of 7

FISH/Roo	om Concern	Findings	Recommendation	Responsible	Priority
210	Temp X - Humidity	74 RH% 67.2 CO2 955 Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
212	Temp Classroom is dusted/vacuumed thoroughly and regularly?	74.3 RH% 68.9 CO2 951 General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
213	Temp Classroom is dusted/vacuumed thoroughly and regularly?	72.1 RH% 73.3 CO2 955 General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
	X - Plants	Live plants in room.	Remove live plants from room. Soil is a source of microbial growth.	Site	2
	X - Scented candle on a hot plate.	Non-approved chemicals, scented cleaners or air fresheners found at the time of the assessment.	Remove non-approved chemicals, scented cleaners and air fresheners from room.	Site	2
214	Temp Classroom is dusted/vacuumed thoroughly and regularly?	72.8 RH% 70.1 CO2 907 General cleanliness Issues were identified at the time of the assessment	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2

Beachside Montessori Village Page 5 of 7

FISH/Room	m Concern	Findings	Recommendation	Responsible	Priority
221	Temp Classroom is free of significant temperature shifts?	72.8 RH% 70.4 CO2 1002 Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
	Temperature in my classroom is generally comfortable (72F-78F)?	No issues were identified at the time of the assessment.	None at this time.		
232	Temp Bathroom exhaust fan is functioning properly?	72.4 RH% 75 CO2 647 No issues were identified at the time of the assessment.	None at this time.		
	Room is free of smell of chemicals?	No issues were identified at the time of the assessment.	None at this time.		
	X - Humidity	Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	РРО	2
	X - Non-approved chemicals	Non-approved chemicals, scented cleaners or air fresheners found at the time of the assessment.	Remove non-approved chemicals, scented cleaners and air fresheners from room.	Site	2
	X - Plants	Live plants in room.	Remove live plants from room. Soil is a source of microbial growth.	Site	2
235	Temp Air supply/return registers are cleaned regularly and free of dust and debris accumulation?	72.8 RH% 74.6 CO2 676 No issues were identified at the time of the assessment.	None at this time.		
	Classroom is dusted/vacuumed thoroughly and regularly?	General cleanliness Issues were identified at the time of the assessment Minor dust	Custodial staff to address general cleanliness issues. Dusting, mopping, trash removal, etc.	Site	2
	Classrooms general appearance is clean and acceptable?	No issues were identified at the time of the assessment.	None at this time.		

Beachside Montessori Village Page 6 of 7

FISH/Room	m Concern		Findings	Recommendation	Responsible	Priority
235		Temp	72.8 RH% 74.6 CO2 676			
	X - Humidity		Humidity was elevated at the time of the assessment South Area working on ongoing A/C issues	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
261		Temp	76.2 RH% 66.7 CO2 551			
	Bathroom exhaust fan is functioning properly?		No issues were identified at the time of the assessment.	None at this time.		
	X - Humidity		Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	PPO	2
			South Area working on ongoing A/C issues			

Beachside Montessori Village Page 7 of 7