Tools for Schools - Indoor Air Quality

Follow-up Action Plan for Site

Site Site

Site

Priority

2

Room

101L

125

863VE

PM15

Broadview Elementary Principal: Mrs. Mary Morgan

Walkthrough Date: 4/14/2004

Air freshener in room.

No water in trap.

04	Temp RH Co2 Outside Measurements	Assignment Member: Mark Dorsett
Responsible	Assessment Comments	Recommended Corrective Action
Site	Needs IAQ manual.	Contact EPA website www.epa.gov/iaq
Site	Odors coming from restroom.	Reset toilet in restroom.

Remove air freshener.

Fill trap with water.

8/18/2005 **Sorted by Room and Priority** Page 1 of 1 **Broadview Elementary**