Report: Site KING MARTIN LUTHER ELEMENTARY

Outdoor Parameters: 75.9 54.3 565

Room	Priority	Responsible	Answer	Recommendation
101	Inside Parameters:	Temp	RH	CO2
		73.5	51.8	1064
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
101C	Inside Parameters:	Temp	RH	CO2
		71.2	52.1	1062
	2	Site	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
Room	Priority	Responsible	Answer	Recommendation
107	Inside Parameters:	Temp	RH	CO2
		73.1	51.8	854
	1		Non-approved chemicals, scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals, scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
119	Inside Parameters:	Temp	RH	CO2
		73.4	53.1	1200
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

Page 2 of 6

Room	Priority	Responsible	Answer	Recommendation
122	Inside Parameters:	Temp	RH	CO2
		73.6	52.6	1124
	1	Site	Non-approved chemicals, scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals, scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
132	Inside Parameters:	Temp	RH	CO2
		73.9	53.0	1132
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
142	Inside Parameters:	Temp	RH	CO2
		73.7	52.6	1086
	1	Site	Non-approved chemicals, scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals, scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
144	T 1			
144	Inside Parameters:	Temp	RH	CO2
			RH 53.3	CO2 962
	Parameters:	71.5	53.3 Temperature was low at the time of assessment.	962 Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC
	Parameters:	71.5 Site Responsible Temp	53.3 Temperature was low at the time of assessment. Answer RH	962 Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve. Recommendation
Room	Parameters: 2 Priority Inside Parameters:	71.5 Site Responsible Temp	53.3 Temperature was low at the time of assessment. Answer RH	962 Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve. Recommendation
Room	Parameters: 2 Priority Inside Parameters:	71.5 Site Responsible Temp	53.3 Temperature was low at the time of assessment. Answer RH	962 Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve. Recommendation

9/24/2007

			assessment.	approved germicidal cleaner.
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	1	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	2	Site	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
Room	Priority	Responsible	Answer	Recommendation
302	Inside Parameters:	Temp	RH	CO2
		70.6	53.3	853
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	2	Site	Temperature was low at the time of assessment.	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
	2	Site	Heavy dust and debris on upholstered furniture in room.	Thoroughly clean upholstered furniture.
Room	Priority	Responsible	Answer	Recommendation
307	Inside Parameters:	Temp	RH	CO2
		72.0	52.4	798
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
Room	Priority	Responsible	Answer	Recommendation

http://169.139.254.126/riskmgmt/reports.aspx

Page 4 of 6

308	Inside Parameters:	Temp	RH	CO2
Ï		71.6	52.7	728
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	2	Site	Ceiling tiles broken, damaged or missing.	Facilities serviceperson to replace ceiling tiles.
	1	Site	Non-approved chemicals, scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals, scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
309	Inside Parameters:	Тетр	RH	CO2
		72.6	52.2	727
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
Room	Priority	Responsible	Answer	Recommendation
312	Inside Parameters:	Temp	RH	CO2
		72.6	52.1	734
. <u> </u>	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
Room	Priority	Responsible	Answer	Recommendation
316	Inside Parameters:	Temp	RH	CO2
		70.5	53.0	734
	2	Site	Dust observed on return register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
Room	Priority	Responsible	Answer	Recommendation
318	Inside Parameters:	Temp	RH	CO2

http://169.139.254.126/riskmgmt/reports.aspx

		71.1	52.7	1117
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
	1	Site	Non-approved chemicals, scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals, scented cleaners or air fresheners from the room.
Room	Priority	Responsible	Answer	Recommendation
324	Inside Parameters:	Temp	RH	CO2
		71.5	52.7	838
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
Room	Priority	Responsible	Answer	Recommendation
	<u>I Horney</u>	Responsible	Answei	Kecommendation
325	Inside Parameters:	Temp	RH	CO2
	Inside	Temp		
	Inside	Temp	RH	CO2
	Inside Parameters:	Temp 72.7	RH 52.6 Dust observed on supply register at the time of	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District
	Inside Parameters:	Temp 72.7 Site	RH 52.6 Dust observed on supply register at the time of assessment.	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	Inside Parameters: 2 2	Temp 72.7 Site Site	RH 52.6 Dust observed on supply register at the time of assessment. Dust and dirt accumulation on floor. This is a general issue requiring approved	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner. Facilities serviceperson to thoroughly clean and sanitize. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify
325	Inside Parameters: 2 2 3	Temp 72.7 Site Site Site	RH 52.6 Dust observed on supply register at the time of assessment. Dust and dirt accumulation on floor. This is a general issue requiring approved communication among all stakeholders. Art supplies in room.	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner. Facilities serviceperson to thoroughly clean and sanitize. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary. Curriculum supervisor meet with appropriate staff to address issues of concern and ensure that all supplies are approved for use and
325	Inside Parameters: 2 2 3 3	Temp 72.7 Site Site Site Site	RH 52.6 Dust observed on supply register at the time of assessment. Dust and dirt accumulation on floor. This is a general issue requiring approved communication among all stakeholders. Art supplies in room.	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner. Facilities serviceperson to thoroughly clean and sanitize. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary. Curriculum supervisor meet with appropriate staff to address issues of concern and ensure that all supplies are approved for use and handled/stored in a manner consistent with District procedures.
325	Inside Parameters: 2 2 3 3 Priority Inside	Temp 72.7 Site Site Site Site Responsible	RH 52.6 Dust observed on supply register at the time of assessment. Dust and dirt accumulation on floor. This is a general issue requiring approved communication among all stakeholders. Art supplies in room. Answer	CO2 794 Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner. Facilities serviceperson to thoroughly clean and sanitize. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary. Curriculum supervisor meet with appropriate staff to address issues of concern and ensure that all supplies are approved for use and handled/stored in a manner consistent with District procedures. Recommendation

Slight dust accumulation was observed on

Site based administration should address general cleanliness with

	2	Site	environmental surfaces at the time of assessment.	facility serviceperson staff.
Room	Priority	Responsible	Answer	Recommendation
850	Inside Parameters:	Temp	RH	CO2
		75.6	52.4	781
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
Room	Priority	Responsible	Answer	Recommendation
851	Inside Parameters:	Temp	RH	CO2
		76.7	51.9	850
	2	Site	Odor detected at the time of assessment. Room is adjacent to kitchen and/or home economics room.	Facilities serviceperson to evaluate cause of odor and inspect exhaust fans/fume hoods for proper operation.
Room	Priority	Responsible	Answer	Recommendation
853	Inside Parameters:	Temp	RH	CO2
		75.0	52.7	565
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust observed on supply register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
	2	Site	There appears to be a problem with spill clean up practices. To address all spills in a timely manner all moisture effected materials must be dried within a 24-hour timeframe.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
Room	Priority	Responsible	Answer	Recommendation
854	Inside Parameters:	Temp	RH	CO2
		75.9	51.3	759
	2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
	2	Site	Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
	3	Site	This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.