

managing risk with responsibility

Aston A. Henry, Supervisor	Telephone:	754 321-1900	
Risk Management Department	Fax:	754 321-1917	

September 20, 2010 Signature on File

TO: Mr. Donald Gardner, Principal

Park Lakes Elementary School

FROM: Aston A. Henry, Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 210

For Custodial Supervisor Use Only				
Custodial Issues Addressed				
Custodial Issues Not Addressed				

On August 24, 2010, I conducted an assessment of FISH 210 at Park Lakes Elementary School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

Dr. Leontine Butler, Area Superintendent cc:

Dr. Desmond Blackburn, Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Greg Boardman, Project Manager, Facilities and Construction Management

Dane Ramson, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AH/tc Enc.

		IAQ Asse	essment	Location Number	3761	
	Park Lakes Elemer	ntary School		Evaluation Requested	August 24, 2010	
Time of Day 12	:55 pm			Evaluation Date	August 24, 2010	
Outdoor Conditions	Temperature	92.1 R	Relative Humidity	63.8 Ambie	ent CO2 387	
Noticeable Odor Ceiling Type Wall Type Flooring Ceiling Walls Flooring HVAC Supply Grills HVAC Return Grills Ceiling at Supply	74.5 No 2 x 4 Lay In Drywall Tile Clean Minor Dur / Debris Yes No Yes No Yes No No Yes No	Visible water damage / staining? No No No No No No No No No N	Range Visible microgrowth? No No No	bbial Amount o	> Ambient 31 f cted None None None	
Grills Surfaces in Room	Yes No	No				
Disservations Findings - No signs of microbial growth or water intrusion identified at the time of the assessment - No odor detected at the time of the assessment Site Based Maintenance: - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate						