## **Tools for Schools - Indoor Air Quality**

## **Follow-up Action Plan for <u>District Maintenance</u>**

Silver Lakes Elementary 87 57%

Walkthrough Date: 5/21/2004 Temp RH Co2 Assignment Member: Bob Krickovich

**Outside Measurements** 



Principal: Ms. Irene Cejka

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
203	1	District Maintenance	1 stained ceiling tile.	Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
209	1	District Maintenance	Stained ceiling tiles.	Maintenance to inspect for roof leak and repair as appropriate and replace ceiling tiles.
212	1	District Maintenance	Water stains under sink.	Maintenance to inspect for leak and repair as appropriate.

8/19/2005 Silver Lakes Elementary Sorted by Room and Priority Page 1 of 1