

Tools for Schools - Indoor Air Quality

Follow-up Action Plan for Site

Boyd Anderson High

81 57% 220

Principal: Dr. Timothy Gadson



Walkthrough Date: 5/14/2004

Temp RH Co2
Outside Measurements

Assignment Member: Mark Dorsett

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
109	3	Site	Broken wall plate.	Repair or replace wall plate.
109	3	Site	Dirt on partition and vinyl base broken.	Custodial staff to clean partition and call in work order to repair vinyl base.
109	3	Site	Broken ceiling tiles by clock.	Replace ceiling tiles.
109	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
110	2	Site	Air supply vents need to be cleaned.	Custodial staff should clean and sanitize the air supply and return registers in this classroom.
110	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
138	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
163	2	Site	No animals in the classroom. However, excessive household cleaning products were found under sink.	Remove all non SBBC products.
163	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
178	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
188	2	Site	Dust accumulation was observed on environmental surfaces. WD40 found in room.	custodial staff should thoroughly clean all environmental surfaces within classroom. Remove WD40.
211	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
232	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
280	2	Site	Area around supply air vents needs to be clained.	Custodial staff should clean and sanitize the air supply and return registers in this classroom.
280	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
535	3	Site	Needs IAQ manual.	Contact EPA website www.epa.gov/iaq
573	3	Site	temperature was within acceptable range at time of assessment. Learning materials are stored in boxes.	Custodial staff to provide additional storage.

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
951	3	Site	Floors need to be better maintained.	Clean and sanitize flooring.
Bldg 99	3	Site	Dust accumulation was observed on environmental surfaces.	Custodial staff should thoroughly clean all environmental surfaces within classroom.