

Tools for Schools Phase IX - Indoor Air Quality

Follow-up Action Plan for PPO



Coconut Creek High

1681

87.3 63.1 365

Walkthrough Date: 5/14/2012

Temp RH Co2

Outside Measurements

Room	Priority	Concern	Response	Recommendation
101G	2	X	CO2 was elevated at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
102B	2	Room is usually comfortable? (If no, please explain in the notes below.)	CO2 was elevated at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
114A	2	Room is usually comfortable? (If no, please explain in the notes below.)	Environmental parameters were not within acceptable range at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
148	2	Room is free of smell of mold or mildew?	Odor detected at the time of the assessment	Evaluate for cause of odor and initiate repairs as necessary.
148	2	Other exhaust fans that may exist in the classroom are functioning properly?	Exhaust fans not operating properly.	Evaluate exhaust fans and repair as appropriate.
185A	2	Classroom is free of significant temperature shifts?	CO2 was elevated at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
232	2	X	CO2 was elevated at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.
236	2	X	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.
254	2	Classroom is free of significant temperature shifts?	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.