Tools for Schools Phase II - Indoor Air Quality

Follow-up Action Plan for Physical Plant Operations

Everglades High 85.4 50.5 429 **Principal:** Dr. Paul Fetscher

Walkthrough Date: 5/12/2005 Temp RH Co2
Outside Measurements



Room	Priority	Responsible	Response	Recommendation
350	1	Physical Plant Operations	Water damage under window.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
388	1	Physical Plant Operations	Condensation on windows at the time of assessment. Temperature was within acceptable range and leaks were identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
388	1	Physical Plant Operations	Water damage under window.	Physical Plant Operations to evaluate for leaks and repair as appropriate.

8/16/2005 Everglades High Sorted by Room and Priority Page 1 of 1