

# Tools for Schools - Indoor Air Quality

## Follow-up Action Plan for Site



Fort Lauderdale High

84.5 55% 190

Principal: Ms. Gina Eyerman

Walkthrough Date: 5/4/2004

Temp RH Co2  
Outside Measurements

Assignment Member: Mark Dorsett

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
1276	3	Site	Requested IAQ information.	Contact EPA website <a href="http://www.epa.gov/iaq">www.epa.gov/iaq</a>
192	2	Site	Temperature too cold at times.	Custodial staff to set thermostat.
192	3	Site	Requested IAQ information.	Contact EPA website <a href="http://www.epa.gov/iaq">www.epa.gov/iaq</a>
196	3	Site	A/C system has been repaired. Supply vent is rusty.	Custodial staff will replace supply vent.
196	3	Site	Teacher advised has improved.	Custodial staff should thoroughly clean all environmental surfaces within classroom.
204	3	Site	Teacher reported the room is generally too cold. Temperature was within recommended range.	Custodial staff to set thermostat.
825	2	Site	Room is too cold.	Custodial staff to adjust thermostat.