

Tools for Schools Phase II - Indoor Air Quality

Follow-up Action Plan for Physical Plant Operations



Hallandale High

86.2 61.6 565

Principal: Ms. Rosemary Chambers

Walkthrough Date: 5/19/2005

Temp RH Co2
Outside Measurements

Room	Priority	Responsible	Response	Recommendation
417	2	Physical Plant Operations	Air supply/return ventilation is not functioning qualitatively.	Physical Plant Operations to evaluate need for test and balance.
601B	2	Physical Plant Operations	Carpet was stained.	Physical Plant Operations to evaluate and repair as appropriate.
804	1	Physical Plant Operations	Odor detected and microbial growth identified. Carpet is stained.	Physical Plant Operations to evaluate cause of microbial growth and repair and remediate as appropriate.
804	2	Physical Plant Operations	Exhaust fan is not functioning properly.	Physical Plant Operations to evaluate and repair as appropriate.