

Report: *Site***MCARTHUR HIGH**

Walkthrough Date: 05/08/2006 Temp RH CO2

Outdoor Parameters: 89.6 45.6 528

Room	Priority	Responsible	Answer	Recommendation
001	Inside Parameters:	Temp	RH	CO2
		78.1	49	795

2	Site	Dust observed on return register at the time of assessment.	Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.
2	Site	No leaks identified. Signs of previous water intrusion as evidenced by stained ceiling tiles.	Facilities serviceperson to replace ceiling tiles.

Room	Priority	Responsible	Answer	Recommendation
096	Inside Parameters:	Temp	RH	CO2
		73.7	48.9	1365

2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
2	Site	Dust and dirt accumulation on floor. This is a hallway.	Facilities serviceperson to thoroughly clean and sanitize.

Room	Priority	Responsible	Answer	Recommendation
411	Inside Parameters:	Temp	RH	CO2
		78.6	44.1	1567

1	Site	This is a general issue requiring approved communication among all stakeholders.	Dust as needed.
		No odor detected at the time of	Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition

2 Site assessment. Temperature was slightly elevated. and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

Room	Priority	Responsible	Answer	Recommendation
428	Inside Parameters:	Temp	RH	CO2
		76.8	46	1600

2 Site Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment. Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts

Room	Priority	Responsible	Answer	Recommendation
431	Inside Parameters:	Temp	RH	CO2
		77.4	77	1460

2 Site Dust and dirt accumulation on floor. Facilities serviceperson to thoroughly clean and sanitize.

Room	Priority	Responsible	Answer	Recommendation
502	Inside Parameters:	Temp	RH	CO2
		71.5	52.8	650

2 Site Excessive dust accumulation was observed on environmental surfaces at the time of assessment. Site based administration should address general cleanliness with facility serviceperson staff.

2 Site Dust observed on supply register at the time of assessment. Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

2 Site Water is not poured down floor drain at least once a week. Site based administration should address maintenance of sinks toilets and drains with facility serviceperson staff.

2 Site Temperature was low at the time of assessment.

Site based administration to encourage facility serviceperson staff to adjust the thermostat. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

Room	Priority	Responsible	Answer	Recommendation
806	Inside Parameters:	Temp	RH	CO2
		71.9	58.1	847

2 Site Slight dust accumulation was observed on environmental surfaces at the time of assessment.

Site based administration should address general cleanliness with facility serviceperson staff.

2 Site Dust observed on return register at the time of assessment.

Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.

2 Site Dust and dirt accumulation on floor.

Facilities serviceperson to thoroughly clean and sanitize.

Room	Priority	Responsible	Answer	Recommendation
814	Inside Parameters:	Temp	RH	CO2
		71.9	49.3	833

1 Site Stuffed animals in room. Dust accumulation on surfaces.

Remove stuffed animals from room. Site based administration should address general cleanliness with facility serviceperson staff.

1 Site Water to be poured drains.

Pour water down drains weekly.

2 Site It appears as though sink is not utilized regularly. Sewer gas odor detected. By running water regularly it eliminates the potential for sewer gas odors.

Site based administration should address maintenance of sinks toilets and drains with facility serviceperson staff.

2 Site No leaks identified. Signs of previous water intrusion as evidenced by stained ceiling tiles.

Facilities serviceperson to replace ceiling tiles.

Room	Priority	Responsible	Answer	Recommendation
922	Inside Parameters:	Temp	RH	CO2

		74.5	49.7	860
2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.		Site based administration should address general cleanliness with facility serviceperson staff.
2	Site	Dust and dirt accumulation on floor.		Facilities serviceperson to thoroughly clean and sanitize.
3	Site	This is a general issue requiring approved communication among all stakeholders.		Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
3	Site	This is a general issue requiring approved communication among all stakeholders.		Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

Room	Priority	Responsible	Answer	Recommendation
931	Inside Parameters:	Temp	RH	CO2
		75.2	49.1	1433

2	Site	Slight dust accumulation was observed on environmental surfaces at the time of assessment.		Site based administration should address general cleanliness with facility serviceperson staff.
---	------	--	--	---

Room	Priority	Responsible	Answer	Recommendation
935	Inside Parameters:	Temp	RH	CO2
		73.4	52.9	1381

3	Site	This is a general issue requiring approved communication among all stakeholders.		Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
---	------	--	--	--

1	Site	Non-approved chemicals scented cleaners or air fresheners found at the time of assessment.		Facilities serviceperson to remove all non-approved chemicals scented cleaners or air fresheners from the room.
---	------	--	--	---

Room	Priority	Responsible	Answer	Recommendation
943	Inside Parameters:	Temp	RH	CO2

		75.2	49.3	1494
2	Site		Slight dust accumulation was observed on environmental surfaces due to clutter at the time of assessment.	Site based administration should work with room occupant to encourage occupant to reduce clutter to assist facility serviceperson with their dusting efforts
1	Site		Non-approved chemicals scented cleaners or air fresheners found at the time of assessment.	Facilities serviceperson to remove all non-approved chemicals scented cleaners or air fresheners from the room.

Room	Priority	Responsible	Answer	Recommendation
944	Inside Parameters:	Temp	RH	CO2
		75.7	48.6	1431

2	Site		Slight dust accumulation was observed on environmental surfaces at the time of assessment.	Site based administration should address general cleanliness with facility serviceperson staff.
2	Site		Dust and dirt accumulation on floor.	Facilities serviceperson to thoroughly clean and sanitize.
3	Site		This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
1	Site		Microwave in cabinet contributes to odors.	Remove or re-position the microwave.

Room	Priority	Responsible	Answer	Recommendation
949	Inside Parameters:	Temp	RH	CO2
		74.3	48.8	1215

3	Site		This is a general issue requiring approved communication among all stakeholders.	Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.
---	------	--	--	--

Room	Priority	Responsible	Answer	Recommendation
961	Inside Parameters:	Temp	RH	CO2
		73.7	49.5	1535

1 Site Non-approved chemicals scented cleaners or air fresheners found at the time of assessment. Facilities serviceperson to remove all non-approved chemicals scented cleaners or air fresheners from the room.

Room	Priority	Responsible	Answer	Recommendation
972	Inside Parameters:	Temp	RH	CO2
		73.8	49	1696

2 Site Slight dust accumulation was observed on environmental surfaces at the time of assessment. Site based administration should address general cleanliness with facility serviceperson staff.

2 Site Dust observed on supply register at the time of assessment. Facilities serviceperson to thoroughly clean and sanitize with District approved germicidal cleaner.

2 Site Dust and dirt accumulation on floor. Facilities serviceperson to thoroughly clean and sanitize.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

Room	Priority	Responsible	Answer	Recommendation
981	Inside Parameters:	Temp	RH	CO2
		72.9	50.4	1562

2 Site Dust and dirt accumulation on floor. Facilities serviceperson to thoroughly clean and sanitize.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

3 Site This is a general issue requiring approved communication among all stakeholders. Site based administration is encouraged to communicate all known student allergies to the appropriate personnel in order to modify classroom activities/conditions when necessary.

2 Site No leaks identified. Signs of previous water intrusion as evidenced by stained Facilities serviceperson to replace ceiling tiles.

ceiling tiles.