

Tools for Schools - Indoor Air Quality

Follow-up Action Plan for Site



Crystal Lake Middle

Principal: Mr. James Neer

Walkthrough Date: 4/16/2004

Temp RH Co2
Outside Measurements

Assignment Member: Mark Dorsett

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
130	2	Site	Ceiling tiles are stained.	Install new ceiling tiles.
131	2	Site	Ceiling tiles are stained.	Install new ceiling tiles.
131	2	Site	Sink is stopped up.	Unclog sink.
134	2	Site	Plants identified in Media Center.	Remove plants.
136	2	Site	Household cleaning products identified.	Remove all non-SBBC cleaning products.
201	3	Site		Contact EPA website www.epa.gov/iaq
P-2	3	Site		Site based administration will provide information to site based staff.
P-2	3	Site		Site based administration will provide information to site based staff.
P-2	3	Site		Site based administration will provide information to site based staff.
P-2	3	Site		Site based administration will provide information to site based staff.