THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

October 4, 20	17 Signature on File	For Custodial Supervisor Use Only
ТО	Amy Winder, Principal Indian Trace Elementary	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Alison Witoshynsky, Project Manager Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On October 3, 2017, I conducted an assessment at **Indian Trace Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ Assessment did not identify any existing conditions significantly impacting IAQ or presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to allergens and / or conditions noted during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of any item/s identified and noted in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations

Shelley Meloni, Director, Pre-Construction

Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division

Greg Neiman, Area Supervisor, Zone 1

Kurt Wirz, Area Manager Trades

Gerald Devio, Supervisor II Custodial

Benjamin Osborne, Supervisor II Custodial

Mark Murray, Supervisor II Custodial

Broward Teachers Union

Federation of Public Employees

Multiple Room IAQ Assessment

Indian Trace Elementary School Evaluation Date October 3, 2017 Time of Day 1020						
Outdoor Conditions	Temperature	86.1 Relative	Humidity 80.1	Ambient CO2 43	39	
Fish # of rooms a 504, 505, 506, 507, 50						
Temperature Range in Relative Humidity F	Range in the Room	s Assessed was Between	54.2 And 59	Acceptable 72 - 7 Acceptable 72 - 7 Acceptable 80% - 9.4 Acceptable MAX 7 Range Ambi	60%	
Noticeable Odor Ceiling 2' X 4' Walls Dryv Floor 12" x 12	vall	Visible water damage / staining? No No No	Visible microbial growth? No No No	Amount of material affected		
Ceiling Clean Walls Clean Flooring Clean Room Surfaces Clean	Yes Yes Yes	HVAC Supply Grills Clean Inside of Supply Duct Clean Ceiling at Supply Grills Clean	Yes Yes Yes	HVAC Return Grills Clean Inside of Return Duct Clean	Yes N/A	
Signs of Pests	Yes No	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is	Yes Yes N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No	
		in Sealed Containers				

Multiple Room IAQ Assessment

manipio it	OUIII IAQ A	3303311101	10		
Indian Trace Elementary School	valuation Date	October	3, 2017	Time of Day	1020
Outdoor Conditions Temperature 86.1	Relative H	lumidity	80.1	Ambient CO2	439
HVAC System					
Mechanical Equipment Location Above Ceiling				Mechanical Room Clea	n N/A
Filters Installed Properly Yes Fil	ters Clean	Yes		Inside of HVAC Unit Clea	n N/A
Condensate Pan Clean N/A Cooling	Coil Clean	N/A		N/A in this section = Not A	Accessible
Fresh Air Intake Location Exterior Ceiling So	offit		▼	Fresh Air Intake Fre	e Yes
Pollutant Sources Near Air Intake			▼	of Obstruction	[165
Observations					
Occupants report a foul smell from the Toilet/Sink a wet building materials identified. Exhaust fan (restithough there is a significant amount of stuff/items t	ooms) appea	rs to be ope	erating p		
Corrective Actions to be Completed by Site Based Encourage occupant to reduce clutter Run water in sinks and floor drains monthly	Staff	Correct	ive Actio	ons to be Completed by	PPO V
Run water in sinks and noor drains monthly	 				▼
					▼
	▼				▼
	▼				▼
	→				▼
	 ▼ -				▼
	 				▼