

**THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA**

**ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT**

**TELEPHONE (754) 321-4200**

**FACSIMILE: (754) 321-4285**

August 13, 2015 Signature on File

TO: Carol Lesser, Principal  
**Nova Eisenhower**

FROM: Robert Krickovich, Coordinator, LEA  
Environmental Health & Safety Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed
<hr/>	
<hr/>	

On August 12, 2015, I conducted an assessment at **Nova Eisenhower Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing h2015-ealth factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

*Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.*

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

cc: Shelley Meloni, Director, Pre-Construction  
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division  
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division  
Aston Henry, Director, Risk Management  
Broward Teachers Union  
Federation of Public Employees

RK/jj  
Enc.

# IAQ Assessment

Nova Eisenhower Elementary

Evaluation Date August 12, 2015

Time of Day 2:20 PM

Outdoor Conditions Temperature 94.1

Relative Humidity 47.7

Ambient CO2 447

Fish	Temperature	Range	Relative Humidity	Range	CO <sup>2</sup>	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">854</span>	<span style="border: 1px solid black; padding: 2px;">70.2</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">49.3</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">575</span>	<span style="border: 1px solid black; padding: 2px;">MAX 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">3</span>
Noticeable Odor		<span style="border: 1px solid black; padding: 2px;">No</span>	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	<span style="border: 1px solid black; padding: 2px;">2' X 4' Lay in</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">5 tiles</span>
Walls	<span style="border: 1px solid black; padding: 2px;">Drywall</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">6 sq ft</span>
Floor	<span style="border: 1px solid black; padding: 2px;">12" x 12" Vinyl</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">6 sq ft</span>
Ceiling Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	HVAC Supply Grills Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	HVAC Return Grills Clean	
Walls Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Inside of Supply Duct Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Inside of Return Duct Clean	
Flooring Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Ceiling at Supply Grills Clean		<span style="border: 1px solid black; padding: 2px;">N/a</span>		
Room Surfaces Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>					
Trash Removed		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Exhaust Fans Working		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Unapproved Chemicals / Cleaners in Room	
Signs of Pests		<span style="border: 1px solid black; padding: 2px;">No</span>	Drain Traps Wet		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Air Fresheners in Room	
Room Cluttered		<span style="border: 1px solid black; padding: 2px;">No</span>	Food if Stored in Room is in Sealed Containers		<span style="border: 1px solid black; padding: 2px;">N/A</span>		
Mechanical Equipment Location			<span style="border: 1px solid black; padding: 2px;">Bard back of room</span>			Mechanical Room Clean	
Filters Installed Properly		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Filters Clean		<span style="border: 1px solid black; padding: 2px;">Yes</span>	Inside of HVAC Unit Clean	
Condensate Pan Clean		<span style="border: 1px solid black; padding: 2px;">N/A</span>	Cooling Coil Clean		<span style="border: 1px solid black; padding: 2px;">N/A</span>		
Fresh Air Intake Location			<span style="border: 1px solid black; padding: 2px;">Outside of Room</span> ▼			Fresh Air Intake Free of Obstruction	
Pollutant Sources Near Air Intake			<span style="border: 1px solid black; padding: 2px;">None</span> ▼			<span style="border: 1px solid black; padding: 2px;">Yes</span>	

**Observations**

**Roof leaks - School says work order has been in for months and no one has been out yet - 5 stained ceiling tiles - 100 square feet of water damaged wall material - East wall from restroom out 10 feet into classroom is wet, minor microbial growth at bottom foot of wall - paint inside bathroom east wall in corner water damaged blistered.**

**Corrective Actions to be Completed by Site Based Staff**

	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

**Corrective Actions to be Completed by PPO**

Repair / replace roofing	▼
Remove water damaged ceiling tiles and replace	▼
Remove and replace water damaged drywall	▼
above ceiling	▼
Remove and replace water damaged drywall	▼
east wall	▼
	▼
	▼