

# Tools for Schools - Indoor Air Quality

## Follow-up Action Plan for Project Manager

Eisenhower Elementary

84 50%

**Principal:** Ms. Cindy Frisch



**Walkthrough Date:** 5/13/2004

Temp RH Co2  
**Outside Measurements**

**Assignment Member:** Bob Krickovich

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
852	3	Project Manager	Milk cartons on floor under desks used for storage. Floor tile stained and dirty.	Site based staff to clean and wax floor. Floor tile in bad condition (facility warranty)
853	3	Project Manager	Ceiling tile with hole cut out.	Facility warranty
854	3	Project Manager	Ceiling tile with hole cut out.	Open box to be closed.
854	3	Project Manager	Floor tile dirty and stained. Not holding wax.	Site based staff to clean and wax floor. Facilities check tile not holding wax
M851	3	Project Manager	Hole in ceiling tile cut for smoke detector, not installed in that tile.	Replace ceiling tile.
M851	3	Project Manager	Floor tile stained and dirty. Damaged and chipped.	Site based staff to clean and wax floor. Facilities to repair/replace damaged floor.