

Outdoor Parameters: Temp 63.5 RH 42 CO2 0

FISH	Answer	Recommendation
<input type="button" value="Submit"/>		
127	Sink faucet is loose at deck.	Physical Plant Operations to evaluate and repair as appropriate to prevent leak.
149	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
164	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
201	Caulking around window is damaged/missing.	Physical Plant Operations to reseal around window.
203	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
215	Signs of water intrusion at windows.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
	Rust stains on top window.	Physical Plant Operations to evaluate and repair as appropriate.
346V	Rust staining on light fixtures.	Physical Plant Operations to repair/replace as appropriate.
745V	Ceiling tiles buckling.	Physical Plant Operations to evaluate and repair as appropriate.
	Water intrusion in wall around A/C units.	Physical Plant Operations to repair/replace A/C units as appropriate and repair/replace wall material as necessary.