THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

October 28,	2016 Signature on File	For Custodial Supervisor Use Only
TO:	Riquelme Antonio Rodriguez, Principal Sea Castle Elementary	Custodial Issues Addressed
	Sea Castre Elementary	Custodial Issues Not Addressed
FROM:	Robert Krickovich, Coordinator, LEA Environmental Health & Safety Department	
SUBJECT:	Indoor Air Quality (IAQ) Assessment	

On October 24, 2016, I conducted an assessment at **Sea Castle Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

RK:smn

Enc.

cc: Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Broward Teachers Union

Federation of Public Employees
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Rich Volpi, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Sam Bays, Director, Maintenance Operations
Kurt Wirz, Area Manager Trades

Remove and replace A/C Filters				
Clean Supply Grills with Wexcide				
Clean ceilings around HVAC supply grills				
	▼			
	lacksquare			
	▼			
	lacksquare			

Replace ceiling tiles at supply grills (cuts)				
Evaluate and repair HVAC system as needed				
Repair HVAC to Reduce Humidity Levels	▼			
	▼			
	▼			
	▼			
	▼			
	▼			

Remove and replace A/C Filters	▼		
Clean Supply Grills with Wexcide			
Clean ceilings around HVAC supply grills	▼		
	▼		
	▼		
	▼		
	▼		
	▼		

Corrective Actions to be completed by 110	
Replace ceiling tiles at supply grills (cuts)	▼
Evaluate and repair HVAC system as needed	▼
Repair HVAC to Reduce Humidity Levels	▼
	▼
	•
	•
	▼
	▼

IAQ Assessment

Sea Castle Elementary

Evaluation Date October 24, 2016

Time of Day

10:00

Outdoor Conditions	Tempe	erature	75.0	Relat	ive Humidity	75.4	Ambient CO2	420
		Range 72 - 78	Relative Hum	─ i	Range 30% - 60%	648		Occupants 4
Noticeable Odor	Yes]	Visible water da staining?		Visible m grow		Amount of material affected	
Ceiling 2' X	4' Lay in		No		No			
Walls Di	rywall		No		No			
Floor 12" x	12" Vinyl		No		No	<u> </u>		
Ceiling Clean	Yes		HVAC Su Grills Cle		No		HVAC Return Grills Clean	Yes
Walls Clean Flooring Clean	Yes		Inside of Duct Cle		Yes		Inside of Return Duct Clean	Yes
Room Surfaces Clean	Yes		Ceiling a Grills Cle		y No			
Trash Removed	Yes		Exhaust Fans				Unapproved Chemicals Cleaners in Room	/ No
Signs of Pests	No		Drain T	raps We	et Yes		Air Fresheners	No
Room Cluttered	No		Food if Stored in in Sealed Contai		is N/A		in Room	[140]
Mechanical Equipm	ent Location	n Abov	ve Ceiling				Mechanical Room Clean	N/A
Filters Installed Prop	perly Y	es	Filter	s Clear	No		Inside of HVAC Unit Clear	N/A
Condensate Pan	Clean N	/ A	Cooling Co	oil Clear	N/A			
Fresh Air Intake Loc	ation	Roof	top			▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources No Intake	Pollutant Sources Near Air Intake)			▼	G. G.G., ac., c.,	
Observations								
Musty Odor in room	n - HVAC fil	ters dirt	y - HVAC supply	grills	dirty - Ceilings	s at suppl	y grills dirty	
Corrective Actions	to be Com	pleted b	y Site Based St	aff	Corre	ctive Action	ons to be Completed by F	PPO
	and replac			▼	<u> </u>		tiles at supply grills (cuts	
	pply Grills			▼	-		air HVAC system as need	
Clean ceiling	s around H	VAC su	oply grills	▼			Reduce Humidity Levels	
				▼	Clean e	entire HV <i>F</i>	AC system - unit and drop	os ▼
				V				▼
				H	—			