

Tools for Schools - Indoor Air Quality

Follow-up Action Plan for Site



Apollo Middle

81 60%

Principal: Ms. Aimee Zekofsky

Walkthrough Date: 4/23/2004

Temp RH Co2
Outside Measurements

Assignment Member: Bob Krickovich

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
182	3	Site	Dust accumulation was observed on environmental surfaces. Flooring stained and dirty.	custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
185	3	Site	Dust accumulation was observed on environmental surfaces and flooring is stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
602 (119)	2	Site	Sink traps are dry. Possible sewer gas odor.	Custodial staff advised to fill traps with water.
603 (117)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
606 (114)	3	Site	Dust accumulation was observed on environmental surfaces and stained and dirty flooring.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
701 (122)	3	Site	Water in traps but drains slowly.	Clean strainers in sink.
701 (122)	3	Site	Dust accumulation was observed on environmental surfaces and stained and dirty flooring.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
702 (116)	3	Site	Dust accumulation was observed on environmental surfaces and stained and dirty flooring.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
709 (137)	3	Site	Dust accumulation was observed on environmental surfaces and stained and dirty flooring .	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
803 (145)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
805 (136)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax floor.
P33 (245CX)	3	Site	Condensation in light fixtures by A/C vents.	Direct air away from light fixtures and replace stained ceiling tiles.
P33 (245CX)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
P36 (116C)	3	Site	There were no problems observed at time of assessment. However, there are stains on ceiling tiles from air blowing onto light fixtures.	Direct air away from light fixtures and replace stained ceiling tiles.
P36 (116C)	3	Site	Dust accumulation was observed on environmental surfaces and stained and dirty flooring.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.
P37 (47N)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.

Room	Priority	Responsible	Assessment Comments	Recommended Corrective Action
P39 (38C)	2	Site	Teacher advised that odor is intermittent when the room gets hot and stuffy.	Advised to turn on both A/C units when the classroom is occupied.
P39 (38C)	3	Site	Condensation in light fixtures near A/C vents.	Direct air away from light fixtures.
P39 (38C)	3	Site	Dust accumulation was observed on environmental surfaces and flooring stained and dirty.	Custodial staff should thoroughly clean all environmental surfaces within classroom and clean and wax flooring.